

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21013318/GTF3E2

Date: 12/01/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000020		
Claimant Vehicle No :	FBS3812E	Insured Vehicle No :	SMX1339L		
Date of Loss:	24/12/2021	Nature of Claim:	TP	Claim No:	3144170637SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBS3812E	Engine No:	G3H4E0043516
Make & Model:	YAMAHA XMAX, 250cc ABS	Chassis No:	MH3SG3910MK035611
Reg. Date:	05/04/2021 (Man. Year: 2021)	Odometer:	21286 km
Colour:	Blue		
Engine Capacity:	250 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70-15	Rear Tyre Size:	140/70-14
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	30/12/2021		
Date Inspected:	30/12/2021	Inspected At:	GP Motoring Pte Ltd (HQ) 282 Macpherson Road Singapore 348607
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$16,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT FORK ASSY	Repair	0.00 F	*- F
3	1		*FRONT FORK GARNISH LH	Cut	0.00 F	*- F
4	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
5	1		*FRONT WINDSHIELD LOWER GARNISH	Cut	0.00 F	*- F
6	1		*FRONT WING MIRROR LH	Cut	0.00 F	*- F
7	1		*FRONT LH SIGNAL LAMP	Cracked	0.00 F	*- F
8	1		*HANDLE BAR	Bent	0.00 F	*- F
9	1		*HANDLE BAR GRIP	Necessary	0.00 F	*- F
10	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
11	1		*HAND BRAKE LEVER LH	Cut	0.00 F	*- F
12	2		*SIDE FAIRING LH UPP & LOWER	Cut	0.00 F	*- F
13	1		*REAR FAIRING LH	Cut	0.00 F	*- F
14	1		*STEP BOARD LH	Cut	0.00 F	*- F
15	1		*STEP BOARD SIDE GARNISH	Cut	0.00 F	*- F
16	1		*GRALD HANDLE LH	Cut	0.00 F	*- F
17	1		*REAR BOX	Cut	0.00 F	*- F
18	1		*REAR BOX BRACKET	Repair	0.00 F	*- F
19	1		*STICKER	Necessary	0.00 F	*- F
20	1		*AUTO TRANSMISSION SIDE COVER	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >