

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB21013320/UGA3Q2**Date:** 23/06/2022REFERENCE

| | | | |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | D21MFL0000447 |
| Claimant Vehicle No : | SLE6098K | Insured Vehicle No : | SLW1712J |
| Date of Loss: | 22/12/2021 | Nature of Claim: | TP |
| | | Claim No: | MFL2021D0005663 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|-------------------|
| Reg No: | SLE6098K | | |
| Make & Model: | TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) | Engine No: | 1ZRY322927 |
| Reg. Date: | 27/07/2016 (Man. Year: 2016) | Chassis No: | MR053REH104555698 |
| Colour: | Grey | Odometer: | 114040 km |
| Engine Capacity: | 1598 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Aeolus 6 mm | Rear Left Side: | Aeolus 6 mm |
| Front Right Side: | Aeolus 6 mm | Rear Right Side: | Aeolus 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 2,264.26 | 1,137.48 | 1,126.78 | 49.76 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,950.00 | 1,380.00 | 570.00 | 29.23 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,214.26 | 2,517.48 | 1,696.78 | 40.26 |
| Approved Total (Overridden) (S\$) | | 2,000.00 | | |
| Nett Amount (S\$) | 4,214.26 | 2,000.00 | 2,214.26 | 52.54 |
| + Loss of Use (4.0 x S\$50.00/day) (S\$) | | 200.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 2,207.45 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 30/12/2021 | Quan De Motor Trading BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883 Singapore 417883 |
| Date Inspected: | 30/12/2021 Inspected At: | |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 May 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLE6098K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------|---------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Dented | 621.10 FL | *581.10 FL |
| 2 | 1 | | *REAR BUMPER BEAM | Dented | 472.21 FL | *472.21 FL |
| 3 | 2 | | *REAR BUMPER SIDE RETAINERS | Necessary | 130.00 FL | *130.00 FL |
| 4 | 1 | | *REAR END PANEL | Repair | 645.10 FL | *- FL |
| 5 | 1 | | *REAR END PANEL TOP GARNISH | Serviceable | 285.40 FL | *- FL |
| 6 | 1 | | *TAILLAMP | Not Necessary | 425.20 FL | *- FL |
| 7 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 50.00 FS | *50.00 FS |
| 8 | 1 | | *SET REAR REVERSE SENSOR | Shorted | 280.00 FS | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 2,909.01 | 1,433.31 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 644.75 | 295.83 |
| Total Parts (\$\$) | 2,264.26 | 1,137.48 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO CHECK WIRING | New | 50.00 | 20.00 |
| 2 | TO REMOVE & REFIX REVERSE SENSOR | New | 100.00 | 50.00 |
| 3 | TO REMOVE & REFIX CUSHION UPHOLSTERY | New | 100.00 | 80.00 |
| 4 | TO SPRAY RUST PROOFING | New | 100.00 | 30.00 |
| 5 | LABOUR FOR PANEL BEATING ,WELDING & RENEW PARTS | New | 800.00 | 600.00 |
| 6 | SPRAY PAINTING | New | 800.00 | 600.00 |
| Gross Labour Cost (\$) | | | 1,950.00 | 1,380.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >