

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCG/ARB21013320/4953

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLE 6098K
Quonke

at Workshop m/s

of

Insured:

SLW 1712J

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

852k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4
to

days

Res.: Yes or No

Lum Sum:

to

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

161E
Vehicle: IN / OUT

Date:

Person Contacted:

LAA 3337E

Date / Time

Action / Instruction

Sep 9 2000

14/12 informed Jennifer 2/5 & 2000

Veh No:

SLE 6098K

Yr Regn:

27/7/16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota corolla A/Harc 1598

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

114040

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR03 REH104555698

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Aeo/us

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/1/24

D.O.I.

30/1/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) S + RS SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

) Others

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67

AUTOBAY, SINGAPORE 417883

HP: 96709191

India International Insurance Pte Ltd

64 Cecil Street

#04/#05 IOB Building

Singapore 049711

Attn: Motor Claims Department

Date: 30 December 2021

Accident on 22/12/2021 involving vehicles SLE6098K & SLW1712J

at junction of Tampines Avenue 1 & Avenue 8

Estimate cost of repair to vehicle SLE6098K Toyota Altis 1.6A

1 pc.	rear bumper	581.10	DO	\$ 621.10	
1 pc.	rear bumper beam		DO	\$ 472.21	
2 pcs.	rear bumper side retainers @\$65.00		ner	\$ 130.00	
1 pc.	rear end panel		R	\$ 645.10	X
1 pc.	rear end panel top garnish		su	\$ 285.40	X
1 pc.	taillamp		11	\$ 425.20	X
				\$ 2,579.01	
				Less 25%	\$ 644.75
					\$ 1,934.26

S.Net Items:

1 set	rear bumper clips	ner	\$ 50.00	✓
1 set	rear reverse sensor	shuld	\$ 280.00	200

Labour Charges:

To check wiring	\$ 50.00	20
To remove & refix reverse sensor	\$ 100.00	50
To remove & refix cushion upholstery	\$ 100.00	80
To spray rust proofing	\$ 100.00	30
Labour for panel beating, welding & renew parts	\$ 800.00	600
Spray painting	\$ 800.00	600

Total: \$ 4,214.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
ner
30/12/21
2/3 @ 2000 /
4 days.

P-1183-31
253
887-48
251748