



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4779E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT RH WING MIRROR	MISSING	151.00	151.00
1	FRT RH WING MIRROR BRACKET	BENT	228.00	228.00
1	FRT RH SIGNAL LAMP	CRACKED	193.00	193.00
1	RH HEADLAMP	CRACKED	716.00	716.00
1	FRT RH CORNER PANEL	TO REPAIR SEE LABOUR	214.00	-
1	FRT RH DOOR	TO REPAIR SEE LABOUR	1,160.00	-
1	FRT RH DOOR GLASS	CUT	560.00	450.00
	LESS 15% DISCOUNT		-483.30	-260.70
			2,738.70	1,477.30
<u>SPECIAL NETT ITEMS</u>				
1	BODY STICKER (SN)	NECESSARY	25.00	25.00
1	COMPANY LOGO (SN)	NECESSARY	300.00	200.00
			325.00	225.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT RH CORNER PANEL AND FRT RH DOOR.		800.00	400.00
	SPRAY PAINTING.		800.00	400.00
	TRANSFER DOOR PARTS.	NOT NECESSARY	80.00	-
	REMOVE & REFIT RH DOOR GLASS.		80.00	40.00
	WIRING.		30.00	30.00
			1,790.00	870.00
GRAND TOTAL			4,853.70	2,572.30

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	-----------------

Report Ref No. CS/SMO21013322/Avf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.