

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21013323/RTY3E2

Date: 07/06/2022

REFERENCE

Insured/Claimant: CHIN YEE LEE Policy No: DMPCSNW00041302100
Date of Loss: 17/12/2021 Nature of Claim: OD Claim No: SNM21D207391/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS211D**
Make & Model: MERCEDES-BENZ S400L, 3.0 R19 LED (A) Engine No: 27682530794858
Reg. Date: 26/04/2018 (Man. Year: 2018) Chassis No: WDD2314662F053043
Colour: Black Odometer: 27667 km
Engine Capacity: 2996 cc
Market Value/New Car Price: S\$260,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 R19 Rear Tyre Size: 255/35 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,522.80	7,467.30	12,055.50	61.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	2,060.00	740.00	26.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,322.80	9,527.30	12,795.50	57.32
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	19,322.80	6,527.30	12,795.50	66.22
+ GST 7.00/7.00% (S\$)	1,352.60	456.91	895.69	66.22
Nett Amount (S\$)	20,675.40	6,984.21	13,691.19	66.22

INSPECTION

Date of Assignment: 29/12/2021

Date Inspected: 31/12/2021 Inspected At:

Mova Automotive Pte Ltd
Blk 1008 Bukit Merah Lane 3 #01-04/06/08
Singapore 159722

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$4,297.70 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2022)
Parts:	143	MERCEDES-BENZ S400L 3.0 R19 LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS211D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,760.00 FL	*- FL
2	1		*FRONT BUMPER SENSOR	* Check	295.00 FL	*- FL
3	1		*FRONT BUMPER RETAINER LH	* Check	69.00 FL	*- FL
4	10		*FRONT BUMPER RIVET	Necessary	90.00 FL	*90.00 FL
5	1		*HEADLAMP LH	Not Necessary	5,350.00 FL	*- FL
6	1		*FRONT FENDER LH	Bent	1,850.00 FL	*1,850.00 FL
7	1		*FRONT FENDER MOULDING LH	Not Necessary	205.00 FL	*- FL
8	1		*FRONT FENDER COWLING LH	Not Necessary	417.00 FL	*- FL
9	10		*FRONT FENDER COWLING RIVET LH	Not Necessary	90.00 FL	*- FL
10	1		*ROCKER GARNISH LH	Missing	1,710.00 FL	*1,710.00 FL
11	1		*SET ROCKER GARNISH BRACKET	Necessary	140.00 FL	*140.00 FL
12	1		*ROCKER GARNISH CLAMP KIT	Necessary	280.00 FL	*280.00 FL
13	1		*FRONT ALLOY WHEEL LH	Scratched	1,915.00 FL	*1,915.00 FL
14	1		*FRONT LOWER ARM LH	* Check	1,008.00 FL	*- FL
15	1		*FRONT UPPER ARM LH	* Check	1,330.00 FL	*- FL
16	1		*FRONT KNUCKLE ARM LH	* Check	885.00 FL	*- FL
17	1		*FRONT KNUCKLE BEARING LH	* Check	986.00 FL	*- FL
18	1		*REAR FENDER COWLING LH	Cut	297.00 FL	*297.00 FL
19	10		*REAR FENDER COWLING RIVET	Necessary	100.00 FL	*100.00 FL
20	1		*REAR ALLOY WHEEL LH	Scratched	1,915.00 FL	*1,915.00 FL
21	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
					Sub Total (S\$)	21,692.00 8,297.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	2,169.20 829.70
					Total Parts (S\$)	19,522.80 7,467.30

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE (NPA)	New	0.00	0.00
2	TO CUT & WELD REAR FENDER LH, TO REPAIR REAR INNER PANEL LH, ROCKER PANEL LH, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS	New	1,100.00	800.00
3	TO SPRAY AFFECTED AREAS	New	1,200.00	1,100.00
4	TO REMOVE & REFIX FRONT UNDER CARRIAGE LOWER ARM, UPPER ARM, SHOCK ABSORBER & OTHER ATTACHMENT PARTS (* Check)	New	200.00	0.00
5	TO CHECK WHEEL ALIGNMENT	New	100.00	60.00
6	TO RESET WARNING LIGHT	New	200.00	100.00
Gross Labour Cost (\$\$)			2,800.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >