

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013325/AQY3N2**Date:** 13/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00046432102
Claimant Vehicle No :	SJR9017E	Insured Vehicle No :	GBG214P
Date of Loss:	14/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207343/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR9017E	Engine No:	M16A1469124
Make & Model:	SUZUKI SWIFT, 1.6 (A)	Chassis No:	JSAEZC31S00204361
Reg. Date:	20/07/2009 (Man. Year: 2009)	Odometer:	182876 km
Colour:	White		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45R16	Rear Tyre Size:	205/45R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,374.96	1,766.15	16,608.81	90.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,180.00	1,300.00	3,880.00	74.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,554.96	3,066.15	20,488.81	86.98
Approved Total (Overridden) (\$\$)		2,450.00		
Nett Amount (\$\$)	23,554.96	2,450.00	21,104.96	89.60

INSPECTION

Date of Assignment:	04/01/2022	SR AUTOWORKS PTE LTD (HQ)
Date Inspected:	30/12/2021 Inspected At:	8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit #02-24
Estimated Period of Repair:	5.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2022)
Parts:	144	SUZUKI SWIFT 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR9017E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	580.40 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	266.00 FL	*- FL
3	2		*BONNET HINGE	Not Necessary	242.00 FL	*- FL
4	1		*HEAD LAMP	O/s Cracked	1,074.20 FL	*537.10 FL
5	2		*HEAD LAMP LOWER BRACKET	Not Necessary	315.20 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER	O/s Necessary	197.00 FL	*35.00 FL
7	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	311.00 FL	*- FL
8	1		*FRONT BUMPER FOG COVER RH	Not Necessary	155.90 FL	*- FL
9	1		*FRONT BUMPER UNDER COVER	Not Necessary	317.40 FL	*- FL
10	1		*SUPPORT TOP PANEL	Not Necessary	189.50 FL	*- FL
11	2		*SUPPORT SIDE PANEL	Not Necessary	344.00 FL	*- FL
12	1		*HEAD LAMP TOP PANEL RH	Not Necessary	98.10 FL	*- FL
13	1		*CONDENSER SIDE GARNISH RH	Not Necessary	96.40 FL	*- FL
14	1		*AIR CON CONDENSER	Not Necessary	597.00 FL	*- FL
15	1		*AIR CON PIPE	Not Necessary	157.40 FL	*- FL
16	1		*RADIATOR	Not Necessary	654.00 FL	*- FL
17	1		*WIPER TANK	Not Necessary	121.00 FL	*- FL
18	1		*FRONT FENDER RH	Distorted	390.60 FL	*390.60 FL
19	1		*FRONT FENDER EMBLEM(VVTI)	Necessary	89.00 FL	*89.00 FL
20	1		*FRONT FENDER QUARTER COVER RH	Not Necessary	89.00 FL	*- FL
21	1		*FRONT FENDER INNER SHIELD RH	Torn	198.00 FL	*158.00 FL
22	1		*FRONT FENDER INNER HOUSING RH	Not Necessary	657.30 FL	*- FL
23	1		*FRONT LOWER ARM RH	Bent	260.00 FL	*260.00 FL
24	1		*FRONT KNUCKLE ARM RH	Not Necessary	385.30 FL	*- FL
25	1		*FRONT WHEEL BEARING RH	Damaged	184.60 FL	*184.60 FL
26	1		*FRONT LINKAGE RH	Not Necessary	237.10 FL	*- FL
27	1		*FRONT DRIVE SHAFT RH	Not Necessary	985.00 FL	*- FL
28	1		*STEERING RACKAND PINION	Not Necessary	1,350.00 FL	*- FL
29	1		*SIDE SKIRT RH	Not Necessary	745.00 FL	*- FL
30	1		*FRONT DOOR RH	Not Necessary	795.30 FL	*- FL
31	2		*FRONT DOOR FRAME SIDE BLACK STICKER RH	Not Necessary	190.00 FL	*- FL
32	1		*FRONT DOOR SIDE MIRROR RH	Not Necessary	455.00 FL	*- FL
33	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	188.90 FL	*- FL
34	2		*FRONT DOOR HINGE RH	Not Necessary	289.80 FL	*- FL
35	1		*FRONT DOOR CHECKER RH	Not Necessary	137.50 FL	*- FL
36	1		*FRONT DOOR INNER LOCK RH	Not Necessary	311.00 FL	*- FL
37	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	198.00 FL	*- FL
38	1		*FRONT BUMPER	Repair	1,500.00 FS	*- FS
39	1		*FRONT BUMPER CLIPS SET	Necessary	50.00 FS	*30.00 FS
40	1		*FRONT BUMPER UNDER COVER CLIP SET	Necessary	40.00 FS	*30.00 FS
41	1		*HEAD LAMP BLACK STICKER	Necessary	200.00 FS	*50.00 FS
42	1		*SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
44	1		*FRONT GRILLE	Not Necessary	1,200.00 FS	*- FS
45	1		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	40.00 FS	*- FS
46	1		*FRONT FENDER INNER HOUSING SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

5/13/22, 8:35 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT ADJUSTABLE ABSORBER SET	Not Necessary	1,600.00 FS	*- FS
48	1		*SPORT RIM	Not Necessary	1,200.00 FS	*- FS
49	1		*TYRE	Cut	550.00 FS	*250.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					20,452.90	2,014.30
- List Item Discount on L Items 15.00/15.00% (\$)					2,077.94	248.15
Total Parts (\$)					18,374.96	1,766.15
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,600.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	600.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	250.00	40.00
5	REMOVE AND INSTALL RADIATOR AND REFILL COOLANT AND HIGH PRESSURE TEST	New	180.00	0.00
6	REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS	New	150.00	0.00
7	REMOVE AND INSTALL CARPET, SEAT AND INTERIOR	New	450.00	0.00
8	REMOVE AND INSTALL FRONT DOOR PARTS	New	200.00	0.00
9	REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	500.00	150.00
10	TO CHECK FOUR WHEEL ALIGNMENT	New	100.00	80.00
Gross Labour Cost (\$\$)			5,180.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >