

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN		Ref:	CS3/LPC21013330/Gtf3e2	
	300 BEACH ROAD SINGAPORE 1995		Date:	04/01/2022	
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XD 4368H	Veh. Inspected	i	SKZ 5141B
	Policy No.		Coverage (\$)		0.00
	Claim No.	21/21/22/VC05/025299	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		30/12/2021
2.	2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SYLPHY 1.6	c.c		1598
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	MNTBBAB17Z0026622	Colour		RED
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/55 R16	CONTINENTAL		6 mm
	L/H Front Tyre	205/55 R16	CONTINENTAL		6 mm
	R/H Rear Tyre	205/55 R16	CONTINENTAL		6 mm
	L/H Rear Tyre	205/55 R16	CONTINENTAL		6 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S BODY.			
5.	General Information				
	Accident Date	28/12/2021	Inspect Date /	Time	31/12/2021 (12:30 PM)
	Survey held at	PAUL HOE ENTERPRISE PTE LTD			
		1 KAKI BUKIT AVENUE 6, #01-107, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883			
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21013330/Gtf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor