

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013331/TVY3M4**Date:** 30/05/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00170262100		
Claimant Vehicle No :	SJK8201H	Insured Vehicle No :	SBL7777J		
Date of Loss:	25/12/2021	Nature of Claim:	TP	Claim No:	SNM21D207601/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK8201H	Engine No:	G4LEMU125486
Make & Model:	HYUNDAI KONA, OS EV (A)	Chassis No:	KMHK281EVMU070366
Reg. Date:	29/07/2021 (Man. Year: 2021)	Odometer:	6621 km
Colour:	Grey		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,329.60	2,223.92	6,105.68	73.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	880.00	1,880.00	68.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,089.60	3,103.92	7,985.68	72.01
Approved Total (Overridden) (\$\$)		2,500.00		
(\$\$)	11,089.60	2,500.00	8,589.60	77.46
+ GST 7.00/7.00% (\$\$)	776.27	175.00	601.27	77.46
Nett Amount (\$\$)	11,865.87	2,675.00	9,190.87	77.46

INSPECTION

Date of Assignment:	07/01/2022	
Date Inspected:	03/01/2022 Inspected At:	56 LOYANG WAY, #04-04 LOYANG ENTERPRISE BUILDING REPAIRER : AP AUTOMOTIVE SERVICES PTE LTD
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2022)
Parts:	144	HYUNDAI KONA OS EV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK8201H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	795.00 FL	*595.00 FL
2	1		*BUMPER LOGO	Necessary	65.00 FL	*65.00 FL
3	1		*BUMPER LOWER MOLDING	Not Necessary	271.00 FL	*- FL
4	1		*BUMPER UPPER MOLDING	Cut	195.00 FL	*195.00 FL
5	1		*BUMPER COVER	Not Necessary	637.00 FL	*- FL
6	1		*BUMPER LOWER GRILLE WITH SMART CRUISE	Not Necessary	375.00 FL	*- FL
7	1		*BUMPER TOWING COVER	Not Necessary	45.00 FL	*- FL
8	2		*BUMPER RETAINER	N/s & O/s Not Necessary	250.00 FL	*- FL
9	1		*FOG LAMP	Not Necessary	195.00 FL	*- FL
10	1		*FOG LAMP COVER	Not Necessary	85.00 FL	*- FL
11	1		*FRONT IMPACT BAR	Not Necessary	551.00 FL	*- FL
12	1		*AIR DUCT	Not Necessary	78.00 FL	*- FL
13	1		*DAY LIGHT (LED) RH	Cracked	978.00 FL	*478.00 FL
14	1		*HEAD LAMP (LED) RH	Cut	1,924.00 FL	*1,384.40 FL
15	1		*FRONT FENDER RH	Not Necessary	657.00 FL	*- FL
16	1		*FRONT FENDER GARNISH	Not Necessary	257.00 FL	*- FL
17	1		*FRONT FENDER OUTER MOLDING	Not Necessary	224.00 FL	*- FL
18	1		*FRONT FENDER RETAINER	Not Necessary	75.00 FL	*- FL
19	1		*BONNET	Not Necessary	1,763.00 FL	*- FL
20	1		*BONNET OPEN HOOD	Not Necessary	45.00 FL	*- FL
21	1		*BONNET LOCK	Not Necessary	151.00 FL	*- FL
22	2		*BONNET HINGE	Not Necessary	146.00 FL	*- FL
23	1		*BONNET RUBBER	Not Necessary	45.00 FS	*- FS
24	1		*BONNET INSULATOR	Not Necessary	175.00 FS	*- FS
25	1		*FRONT BUMPER CLIP (SET)	Cut	80.00 FS	*30.00 FS
26	1		*HEAD LAMP CLIP (SET)	Necessary	60.00 FS	*20.00 FS
27	1		*FRONT FENDER SEALANT RH	Not Necessary	80.00 FS	*- FS
28	1		*FRONT FENDER INNER TRIM CLIP (SET)	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,282.00	2,767.40
- List Item Discount on L Items 20.00/20.00% (\$)	1,952.40	543.48
Total Parts (\$)	8,329.60	2,223.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS.	New	1,000.00	400.00
2	TO SPRAY PAINT AFFECTED AREA.	New	1,000.00	300.00
3	TUFF COAT.	New	250.00	0.00
4	WIRING AND BULB CHECK.	New	180.00	30.00
5	REMOVE AND REFIX SENSOR AND DISTANCE SETTING.	New	80.00	0.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	250.00	150.00
Gross Labour Cost (\$\$)			2,760.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >