

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI21013332/ATF3N2**Date:** 10/06/2022**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** SMZ64A **Insured Vehicle No :** YP870A

Date of Loss: 30/12/2021 Nature of Claim: TP Claim No: CDMCG21002496

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMZ64A**

Make & Model: MERCEDES-BENZ GL350, 3.0 (A) Engine No: 27492031180554

Reg. Date: 16/11/2017 (Man. Year: 2017) Chassis No: WDC2533462F318973

Colour: Black Odometer: 19947 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/55R19 Rear Tyre Size: 235/55R19

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,256.00	10,373.40	8,882.60	46.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,870.00	1,990.00	880.00	30.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,126.00</b>	<b>12,363.40</b>	<b>9,762.60</b>	<b>44.12</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>22,126.00</b>	<b>9,900.00</b>	<b>12,226.00</b>	<b>55.26</b>

**INSPECTION**

Date of Assignment: 30/12/2021

Date Inspected: 31/12/2021 Inspected At: Tk Motor Workshop (HQ)  
Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt  
Singapore 417883

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2022)
<b>Parts:</b>	143	MERCEDES-BENZ GL350 3.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMZ64A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,490.00 F	*1,915.00 FN
2	12		*FRONT BUMPER CLIP	Necessary	60.00 F	*30.00 FN
3	1		*FRONT BUMPER L/H SIDE RETAINER	Necessary	48.00 F	*48.00 FN
4	2		*FRONT BUMPER L/H PARKING SENSOR	Damaged	312.00 F	*312.00 FN
5	1		*FRONT BUMPER L/H LOWER GARNISH	Not Necessary	98.00 F	*- FN
6	1		*FRONT BUMPER L/H LOWER GARNISH CHROME	Not Necessary	116.00 F	*- FN
7	1		*FRONT BUMPER SPONGE	Cracked	260.00 F	*180.00 FN
8	1		*FRONT L/H HEADLAMP	Cracked	4,000.00 F	*3,500.00 FN
9	1		*FRONT L/H HEADLAMP CLIP	Necessary	48.00 F	*20.00 FN
10	1		*FRONT GRILLE (AMG LINE R19 LED)	Cracked	788.00 F	*788.00 FN
11	1		*FRONT GRILLE EMBLEM	Necessary	178.00 F	*178.00 FN
12	8		*FRONT GRILLE CLIP	Necessary	40.00 F	*40.00 FN
13	1		*FRONT WIPER TANK	Deformed	368.00 F	*258.00 FN
14	1		*FRONT BONNET	Dented	3,218.00 F	*2,343.00 FN
15	2		*FRONT BONNET HINGES	Not Necessary	224.00 F	*- FN
16	1		*FRONT BONNET EMBLEM	Necessary	78.00 F	*78.00 FN
17	1		*FRONT L/H FENDER	Distorted	1,152.00 F	*1,020.00 FN
18	1		*FRONT L/H FENDER INNER SHIELD	Deformed	278.00 F	*278.00 FN
19	1		*FRONT L/H FENDER EMBLEM	Necessary	160.00 F	*160.00 FN
20	1		*FRONT L/H FENDER ARC GARNISH	Deformed	378.00 F	*378.00 FN
21	12		*SIDE SKIRT CLIP	Not Necessary	48.00 F	*- FN
22	1		*FRONT L/H LOWER ARM	Not Necessary	872.00 F	*- FN
23	1		*FRONT L/H KNUCKLE ARM	Not Necessary	732.00 F	*- FN
24	1		*FRONT L/H KNUCKLE HUP & BEARING	Not Necessary	492.00 F	*- FN
25	1		*FRONT L/H SHOCK ABSORBER	Not Necessary	958.00 F	*- FN
26	1		*FRONT L/H SPORT RIM	Not Necessary	1,860.00 F	*- FN

F=Franchise part. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>19,256.00</b>	<b>11,526.00</b>
<b>- Nett Item Discount on N Items 0.00/10.00% (\$\$)</b>	0.00	1,152.60
<b>Total Parts (\$\$)</b>	<b>19,256.00</b>	<b>10,373.40</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO SPRAY PAINTING	New	1,200.00	900.00
2	TO REMOVE AND REFIX FRONT R/H UNDER CARRIAGE	New	380.00	0.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO CONDUCT COMPUTER ALIGHTMENT	New	90.00	80.00
5	TO REMOVE & REINSTALL FRONT BUMPER PARKING SENSOR,POSITION CHECK & TEST FOR FUNCTIONING ALL SENSOR	New	80.00	60.00
6	TO RESET FAULT CODE & CARRY OUT DIAGNOSTIC CHECK	New	120.00	120.00
7	TO PANEL BEATING,WELDING,REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC	New	950.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,870.00</b>	<b>1,990.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >