

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21013336/BQF3E2**Date:** 02/11/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001623522
Claimant Vehicle No :	SMK7567Z	Insured Vehicle No :	SLK3537Z
Date of Loss:	30/12/2021	Nature of Claim:	TP
		Claim No:	267611

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK7567Z	Engine No:	3A92UHN8093
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH001065
Reg. Date:	23/04/2019 (Man. Year: 2018)	Odometer:	213031 km
Colour:	Silver		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,714.20	3,458.80	3,255.40	48.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,530.00	2,080.00	2,450.00	54.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,244.20	5,538.80	5,705.40	50.74
Approved Total (Overridden) (S\$)		4,450.00		
(S\$)	11,244.20	4,450.00	6,794.20	60.42
+ GST 7.00/7.00% (S\$)	787.09	311.50	475.59	60.42
Nett Amount (S\$)	12,031.29	4,761.50	7,269.79	60.42

INSPECTION

Date of Assignment:	30/12/2021	
Date Inspected:	31/12/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	9.0 days	

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Mar 2022)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK7567Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	745.00 FL	*659.00 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Necessary	28.00 FL	*28.00 FL
3	1		*REAR BUMPER LH SIDE RETAINER	Necessary	28.00 FL	*28.00 FL
4	1		*RH TAILLAMP ASSY	Not Damaged	332.00 FL	*- FL
5	1		*RH REAR FENDER	Dented	826.00 FL	*725.00 FL
6	1		*RH REAR FENDER INNER TRIM	Not Damaged	178.00 FL	*- FL
7	1		*RH REAR FENDER SPLASH SHIELD	Not Damaged	48.00 FL	*- FL
8	1		*RH REAR DOOR	Dented	848.00 FL	*848.00 FL
9	1		*RH REAR DOOR FRAME BLACK TAPE	Necessary	23.00 FL	*23.00 FL
10	1		*RH REAR DOOR LOCK	Not Damaged	192.00 FL	*- FL
11	1		*RH REAR DOOR WEATHERSTRIP	Not Damaged	157.00 FL	*- FL
12	1		*RH REAR DOOR INNER TRIM BOARD	Not Damaged	312.00 FL	*- FL
13	1		*RH REAR SPORT RIM	Cut	708.00 FL	*450.00 FL
14	1		*RH REAR WHEEL BEARING	Not Damaged	231.00 FL	*- FL
15	1		*RH REAR SHOCK ABSORBER	Not Damaged	178.00 FL	*- FL
16	1		*REAR AXLE BEAM	Not Damaged	833.00 FL	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
18	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
19	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
20	1		*SET RH REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
21	1		*SET RH REAR FENDER SPLASH SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
22	1		*RH REAR FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
23	1		*RH REAR TYRE	Not Damaged	350.00 FS	*- FS
24	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS
25	1		*SET RH REAR DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
26	1		*RH FRONT DOOR	Dented	845.00 FL	*845.00 FL
27	1		*RH FRONT DOOR FRAME BLACK TAPE	Necessary	26.00 FL	*26.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,368.00	3,822.00
- List Item Discount on L Items 10.00/10.00% (\$)	653.80	363.20
Total Parts (\$)	6,714.20	3,458.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,200.00	1,000.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,200.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	100.00	0.00
5	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	120.00
6	REMOVE AND REPLACE RH REAR DOOR INNER MECHANISM TO ASSIST REPAIR	New	180.00	80.00
7	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	450.00	0.00
8	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM TO ASSIST REPAIR	New	120.00	0.00
9	REMOVE AND REINSTALL ROOF LINING,SEATS,SEAT BELTS AND CARPET TO ASSIST REPAIR	New	380.00	0.00
10	SPRAY PAINTING	New	250.00	0.00
11	LABOUR	New	250.00	0.00
12	REMOVE AND REINSTALL RH FRONT DOOR INNER MECHANISM TO NEW DOOR	New	100.00	80.00
Gross Labour Cost (\$)			4,530.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >