4/19/22, 11:21 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21013342/KEA3Q2

19/04/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070012946 **Claimant Vehicle** SMY1689X Insured Vehicle No: GBJ2585P

No:

Date of Loss: 29/12/2021 Nature of Claim: TP Claim No: 1204529287SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMY1689X

HONDA HR-V, 1.5 (A) Make & Model: Engine No: L15Z71000907

Reg. Date: 27/11/2015 (Man. Year: 2015) Chassis No: MRHRU1810FP000039

Colour: Odometer: 155039 km Metallic Grey

Engine Capacity: 1497 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Rear Left Side: Dunlop 2 mm Goform 8 mm Rear Right Side: Front Right Side: Goform 8 mm Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,904.72	2,214.88	1,689.84	43.28
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,380.00	1,380.00	1,000.00	42.02
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,284.72	3,594.88	2,689.84	42.80
Арр	proved Total (Overridden) (S\$)		2,850.00		
	(S\$)	6,284.72	2,850.00	3,434.72	54.65
	+ GST 7.00/7.00% (S\$)	439.93	199.50	240.43	54.65
	Nett Amount (S\$)	6,724.65	3,049.50	3,675.15	54.65
	+ Loss of Use (5.0 x S\$	660.00/day) (S\$)	300.00		
	+ Doc/S	Search Fee (S\$)	7.45		
	Ne	ett Liability (S\$)	3,356.95		
	Global Sum Settlement (S\$)		3,350.00		

INSPECTION

Date of Assignment: 30/12/2021

Wei Lee Motor Works (HQ)

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-Date Inspected: 03/01/2022 Inspected At:

Singapore 575644

Estimated Period of Repair: 5.0 days

Adjuster: **KENNETH KONG** Manager: Asher Sng Rong Yi NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	997.10 FL	*953.00 FL
2	1		*TAILGATE ABSORBER	Serviceable	131.00 FL	*- FL
3	1		*TAILGATE LOCK	Repair	98.90 FL	*- FL
4	1		*TAILGATE REFLECTOR	N/S Cracked	553.80 FL	*276.90 FL
5	1		*TAILGATE -H LOGO EMBLEM	Necessary	24.70 FL	*24.70 FL
6	1		*TAILGATE -HR-V EMBLEM	Necessary	19.00 FL	*19.00 FL
7	1		*TAILGATE -I-V TEC EMBLEM	Necessary	16.00 FL	*16.00 FL
8	1		*END PANEL	Repair	411.90 FL	*- FL
9	1		*END PANEL TOP GARNISH	Serviceable	65.00 FL	*- FL
10	1		*BOOT WEATHERSTRIP	Serviceable	95.80 FL	*- FL
11	1		*REAR BUMPER	Buckled	532.10 FL	*532.10 FL
12	1		*TAILAMP	N/S Cracked	964.80 FL	*482.40 FL
13	1		*CORNER PANEL LH &RH	N/S Dented / Distorted	332.60 FL	*166.30 FL
14	2		*REAR BUMPER SENSOR	Serviceable	170.00 FL	*- FL
15	2		*CORNER PANEL SENSOR	Serviceable	170.00 FL	*- FL
16	1		*TAILGATE OUTER HANDLE PANEL	Mtg Cracked	298.20 FL	*298.20 FL
F=Fra	anchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	4,880.90	2,768.60
	- List Item Discount on L Items 20.00/20.00% (S\$)				976.18	553.72
				Total Parts (S\$)	3,904.72	2,214.88
			Report was unsubmitt	ed during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE /TRANSFER REAR WINDSCREEN GLASS TO NEW DOOR	New	180.00	120.00
2	TO REMOVE REAR WIPER ASSEMBLY ,TAILGATE TOP SPOILER AND ALL ATTACHMENTS TO NEW DOOR	New	150.00	60.00
3	TO REMOVE DAMAGED PARTS & ATTACHMENT CUT & WELD DAMAGED PANELS TO STRAIGHTEN REAR CHASSIS WHERE NECESSARY REPAIR /RESHAPE DAMAGED AREAS REPLACE /ALIGN ALL PARTS INTO POSITION	New	950.00	500.00
4	PAINTING	New	1,100.00	700.00
	Gross Labour Cost (S\$)		2,380.00	1,380.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >