

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21013343/KYA3Q2**Date:** 20/04/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SMY7738Z**Insured Vehicle No :** SLM1425R

Date of Loss: 17/12/2021

Nature of Claim: TP

Claim No: 4441238962SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMY7738Z**

Make &amp; Model: HONDA FIT, 1.5 HYBRID (A)

Engine No: LEB1441928

Reg. Date: 25/03/2021 (Man. Year: 2018)

Chassis No: GP51334884

Colour: Metallic Grey

Odometer: 15991 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,063.20	732.48	330.72	31.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	935.00	495.00	34.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,493.20</b>	<b>1,667.48</b>	<b>825.72</b>	<b>33.12</b>
<b>+ GST 7.00/7.00% (S\$)</b>	174.52	116.72	57.80	33.12
<b>Nett Amount (S\$)</b>	<b>2,667.72</b>	<b>1,784.20</b>	<b>883.52</b>	<b>33.12</b>
<b>+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		535.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,321.20</b>		

**INSPECTION**

Date of Assignment: 30/12/2021

Date Inspected: 31/12/2021 Inspected At:

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 &amp;

17, AMK Autopoint

Singapore 568047

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,025.00 FL	*710.30 FL
2	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
3	1		*REAR BUMPER CORNER RETAINER RH	Serviceable	84.00 FL	*- FL
4	1		*REAR FENDER SPLASH SHIELD RH	Distorted	165.00 FL	*150.30 FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$)	1,329.00 915.60
					- List Item Discount on L Items 20.00/20.00% (\$)	265.80 183.12
					Total Parts (\$)	1,063.20 732.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT ELECTRICAL CHECK ,TRANSFER BACK UP SENSORS ,REWIRING BUMPER BORING ETC	New	100.00	15.00
2	TO RESPRAY REPAIR REAR WHEEL RIM	New	150.00	60.00
3	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
4	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF REAR O/S FENDER ,INNER PANEL & PART REPLACEMENT	New	550.00	400.00
5	TO RESPRAY AFFECTED AREAS	New	550.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,430.00</b>	<b>935.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >