

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG21013345/AVCE2

Date: 18/05/2022

REFERENCE

Insured/Claimant:	LIN JIA	Policy No:	2100397147		
Date of Loss:	26/12/2021	Nature of Claim:	OD	Claim No:	4329810540SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ8249C		
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Engine No:	CDN408652
Reg. Date:	29/12/2014 (Man. Year: 2014)	Chassis No:	WAUZZZ4G4EN140732
Colour:	White	Odometer:	94812 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$66,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,014.00	13,604.08	7,409.92	35.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,772.00	4,072.00	3,700.00	47.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,786.00	17,676.08	11,109.92	38.59
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	27,986.00	16,876.08	11,109.92	39.70
+ GST 7.00/7.00% (S\$)	1,959.02	1,181.33	777.69	39.70
Nett Amount (S\$)	29,945.02	18,057.41	11,887.61	39.70

INSPECTION

Date of Assignment:	29/12/2021		
Date Inspected:	29/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	2,832.00 FS	*2,265.60 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	276.00 FS	*- FS
3	1	*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
4	1	*FRONT BUMPER GRILLE - LH	Not Necessary	153.00 FS	*- FS
5	1	*FRONT BUMPER END CAP - LH	Not Necessary	39.00 FS	*- FS
6	1	*RADIATOR GRILLE	Cracked	1,332.00 FS	*1,065.60 FS
7	1	*RADIATOR GRILLE COVER	Not Necessary	36.00 FS	*- FS
8	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	99.00 FS	*- FS
9	1	*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	872.00 FS	*- FS
10	2	*FRONT BUMPER GUIDE PIECE - LH / RH	Not Necessary	76.00 FS	*- FS
11	1	*FRONT BUMPER BRACE - LH	Not Necessary	30.00 FS	*- FS
12	1	*FRONT BUMPER TOP COVER	Cracked	123.00 FS	*98.00 FS
13	1	*CAUTION STICKER	Cracked	14.00 FS	*10.88 FS
14	1	*AIR COND STICKER	Not Necessary	30.00 FS	*- FS
15	2	*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
16	4	*FRONT PARKING AID SENSOR SEAL RING - INNER / OUTER	Not Necessary	6.00 FS	*- FS
17	1	*BONNET	Dented	5,436.00 FS	*4,348.80 FS
18	1	*BONNET ATTACHMENT PARTS	Not Necessary	144.00 FS	*- FS
19	2	*BONNET LOCK BAR	Not Necessary	100.00 FS	*- FS
20	1	*BONNET BOWDEN CABLE - CENTER	Not Necessary	58.00 FS	*- FS
21	2	*BONNET LOCK	Not Necessary	427.00 FS	*- FS
22	1	*BONNET HOOD LATCH	Not Necessary	18.00 FS	*- FS
23	2	*BONNET SWITCH	Not Necessary	148.00 FS	*- FS
24	1	*BONNET RELEASE CABLE	Not Necessary	10.00 FS	*- FS
25	1	*BONNET CATCH HOOK	Not Necessary	140.00 FS	*- FS
26	1	*FRONT FENDER - LH	Buckled	1,391.00 FS	*1,112.80 FS
27	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	42.00 FS	*- FS
28	1	*FRONT FENDER STONE GUARD FILM - LH	Necessary	121.00 FS	*96.40 FS
29	1	*FRONT FENDER BRACE - LH	Not Necessary	96.00 FS	*- FS
30	1	*FRONT WHEEL HOUSING LINER - LH	Not Necessary	275.00 FS	*- FS
31	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	80.00 FS	*- FS
32	1	*FRONT WHEEL SPOILER - LH	Torn	264.00 FS	*211.20 FS
33	1	*HEADLIGHT MOUNTING - LH	Cracked	118.00 FS	*94.40 FS
34	1	*HEADLIGHT GAS DISCHARGE - LH	Cracked	3,321.00 FS	*2,656.80 FS
35	1	*LIFT CYLINDER	Not Necessary	236.00 FS	*- FS
36	5	*LIFT CYLINDER HOSE	Not Necessary	191.00 FS	*- FS
37	1	*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
38	1	*SUNDRIES	Not Necessary	250.00 FS	*- FS
39	1	*HEADLIGHT MOUNTING-RH (Supplementary)	Cracked	132.00 FS	*105.20 FS
40	1	*POWER MODULE FOR DAY DRIVING LIGHT (Supplementary)	Contaminated	611.00 FS	*488.80 FS
41	1	*DISCHARGE LAMP CONTROL UNIT (Supplementary)	Contaminated	1,237.00 FS	*989.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 21,014.00 13,604.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER, AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,500.00
3	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	New	3,500.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
Gross Labour Cost (\$\$)			7,772.00	4,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >