

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21013347/AQCN2**Date:** 25/03/2022**REFERENCE**

Insured/Claimant:	CHIANG SE SHENG	Policy No:	1900166714-01	
Date of Loss:	26/12/2021	Nature of Claim:	OD	Claim No: 0747671300SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC205T		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK087931
Reg. Date:	27/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF58KA076953
Colour:	Red	Odometer:	32085 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$158,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,190.00	2,923.60	13,266.40	81.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,472.00	3,602.00	3,870.00	51.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	23,662.00	6,525.60	17,136.40	72.42
+ GST 7.00/7.00% (\$\$)	1,656.34	456.79	1,199.55	72.42
Nett Amount (\$\$)	25,318.34	6,982.39	18,335.95	72.42

INSPECTION

Date of Assignment:	31/12/2021		
Date Inspected:	29/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	228.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	63.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	474.00 FS	*- FS
8	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	36.00 FS	*- FS
9	1		*FRONT FENDER-RH	Dented	1,060.00 FS	*848.00 FS
10	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
11	1		*FRONT FENDER CLOSING ELEMENT-RH	Not Necessary	74.00 FS	*- FS
12	1		*FRONT FENDER BRACKET-RH	Not Necessary	35.00 FS	*- FS
13	5		*POP RIVET	Necessary	17.00 FS	*13.20 FS
14	1		*FRONT FENDER BRACKET CENTER-RH	Not Necessary	49.00 FS	*- FS
15	1		*FRONT FENDER BRACKET END-RH	Not Necessary	35.00 FS	*- FS
16	1		*FRONT FENDER BRACE-RH	Not Necessary	118.00 FS	*- FS
17	1		*FRONT FENDER CHROME TRIM-RH	Necessary	164.00 FS	*130.80 FS
18	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	275.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	169.00 FS	*- FS
20	1		*FRONT WHEEL SPOILER-RH	Not Necessary	73.00 FS	*- FS
21	1		*FRONT FENDER FLEDGE COVER LONG-RH	Not Necessary	36.00 FS	*- FS
22	1		*FRONT FENDER FLEDGE COVER SHORT-RH	Not Necessary	16.00 FS	*- FS
23	1		*HEADLIGHT	Not Necessary	7,902.00 FS	*- FS
24	1		*LIFT CYLINDER-RH	Not Necessary	198.00 FS	*- FS
25	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	86.00 FS	*- FS
26	1		*ALUMINIUM RIM	Not Necessary	1,690.00 FS	*- FS
27	1		*FRONT DOOR CHROME TRIM-RH	Necessary	164.00 FS	*130.80 FS
28	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

16,190.00

2,923.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL RHS DOOR PANEL TRIM.TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
3	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDERS AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
5	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER AND FRONT RHS DOOR	New	3,200.00	1,650.00
6	TO RENEW RHS FRONT RIM.TO CARRY OUR PRE/POST WHEEL ALIGNMENT	New	520.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,472.00	3,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >