

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21013348/AQCE2

Date: 24/06/2022

REFERENCE

Insured/Claimant: LIM SEOK ENG DORIS @ RASHIDAH LIM ABDULLAH Policy No: 1900093312

Date of Loss: 21/12/2021

Nature of Claim: OD

Claim No: 9487221080SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK9856B	Engine No:	CZE850959
Make & Model:	AUDI Q2 SPORT, 1.4 TFSI COD S-TRONIC (A)	Chassis No:	WAUZZZGA0KA038337
Reg. Date:	30/04/2019 (Man. Year: 2019)	Odometer:	29230 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,930.00	7,837.60	7,092.40	47.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,852.00	2,542.00	3,310.00	56.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,782.00	10,379.60	10,402.40	50.05
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	19,982.00	9,579.60	10,402.40	52.06
+ GST 7.00/7.00% (S\$)	1,398.74	670.57	728.17	52.06
Nett Amount (S\$)	21,380.74	10,250.17	11,130.57	52.06

INSPECTION

Date of Assignment: 31/12/2021

Date Inspected: 29/12/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	894.00 FS	*714.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	347.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	197.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	169.00 FS	*135.20 FS
5	1		*FRONT BUMPER END CAP - LH	Not Necessary	59.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Cut	299.00 FS	*238.80 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	156.00 FS	*- FS
8	1		*FRONT WHEEL SPOILER - LH	Not Necessary	34.00 FS	*- FS
9	1		*FRONT BUMPER ADAPTER - LH	Not Necessary	36.00 FS	*- FS
10	1		*RADIATOR GRILLE	Not Necessary	1,411.00 FS	*- FS
11	1		*RADIATOR STRIKER PLATE	Not Necessary	124.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	723.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	78.00 FS	*- FS
14	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	36.00 FS	*- FS
15	1		*FRONT BUMPER TOP COVER	Not Necessary	100.00 FS	*- FS
16	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
17	1		*AIR COND STICKER	Not Necessary	8.00 FS	*- FS
18	1		*HORN - LH	Not Necessary	286.00 FS	*- FS
19	1		*HORN BRACKET - LH	Not Necessary	31.00 FS	*- FS
20	1		*BONNET	Dented	2,789.00 FS	*2,231.20 FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
22	1		*BONNET STRIKER - LH	Not Necessary	110.00 FS	*- FS
23	1		*BONNET IMPACT PROTECTION - CENTER / LH / RH (3PCS)	Necessary	90.00 FS	*71.20 FS
24	1		*BONNET LOCK MICROSWITCH	Not Necessary	214.00 FS	*- FS
25	1		*HEADLIGHT MOUNTING - LH	Not Necessary	118.00 FS	*- FS
26	1		*HEADLIGHT - LH	Cut	4,915.00 FS	*3,932.00 FS
27	1		*HEADLIGHT WASHER ASSY - LH	Not Necessary	142.00 FS	*- FS
28	1		*LIFT CYLINDER HOSE	Not Necessary	182.00 FS	*- FS
29	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	644.00 FS	*514.40 FS
30	1		*RADIATOR AIR GUIDE - LH	Not Necessary	31.00 FS	*- FS
31	1		*RADIATOR AIR GUIDE - UPPER CENTER	Not Necessary	22.00 FS	*- FS
32	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	196.00 FS	*- FS
33	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
34	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 14,930.00 7,837.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS. HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,852.00	2,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >