



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2200950

INV Date 21/02/2022

Reference CC4/FCI21013349/Kea3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SML 1211J
Insured Veh. SMB 3005C
Claim No. D22000002MFBP
Policy No.
Accident Date 27/12/2021
Inspection Date 30/12/2021

Description	Total
Survey Inspection	307.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	307.00
GST (7%)	21.49
Grand Total	328.49

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CC4/FCI21013349/Kea3q2 Date: 21/02/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMB 3005C	Veh. Inspected	SML 1211J
Policy No.		Coverage (\$)	0.00
Claim No.	D22000002MFBP	Excess (\$)	0.00
Assign From	ESTHER	Assign Date	29/12/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT (A)	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GK31346914	Colour	METALLIC DARK BLUE
Odometer	43412 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	BRIDGESTONE	8 mm
L/H Front Tyre	195/55 R15	BRIDGESTONE	8 mm
R/H Rear Tyre	195/55 R15	BRIDGESTONE	8 mm
L/H Rear Tyre	195/55 R15	BRIDGESTONE	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/12/2021	Inspection Date	30/12/2021
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 1211J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	529.60	510.00
2	REAR BUMPER RETAINER @\$18.70	SERVICEABLE	37.40	-
10	REAR BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	341.60	-
1	REAR END PANEL GARNISH	SERVICEABLE	71.60	-
1	REAR SPACE TYRE TOP COVER	SERVICEABLE	229.90	-
1	REAR SPACE TYRE SPONGE	SERVICEABLE	146.60	-
1	TAIL GATE	BENT	885.80	830.60
1	TAIL GATE LOCK	TO REPAIR SEE LABOUR	188.40	-
1	TAIL GATE RUBBER	SERVICEABLE	92.30	-
1	TAIL GATE OUTER HANDLE	CRACKED	112.30	112.30
1	H EMBLEM	NECESSARY	24.70	24.70
1	FIT EMBLEM	NECESSARY	30.50	30.50
1	TAIL GATE TRIM	SERVICEABLE	171.30	-
1	REAR WINDSCREEN MOULDING	NECESSARY	118.50	118.50
1	REAR WIPER ARM	SERVICEABLE	58.00	-
1	REAR WIPER ARM CAP	CRACKED	12.00	12.00
1	REAR WIPER BLADE	SERVICEABLE	43.20	-
1	REAR WIPER MOTOR	SERVICEABLE	225.00	-
	LESS 20% DISCOUNT		-670.74	-334.72
			2,682.96	1,338.88
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER SENSOR (SN)	SCRATCHED	280.00	200.00
1	TUBE REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	40.00	-
1	REAR NO PLATE (SN)	SERVICEABLE	40.00	-
			360.00	200.00
<u>LABOUR</u>				
	TO PUTTY & SPRAY PAINT.		800.00	550.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS .		100.00	100.00

Report Ref No. CC4/FCI21013349/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER TAIL GATE FITTING.		80.00	60.00
	TO CHECK REAR WIRING & WATER LEAKING .		30.00	15.00
	TO ANTI-RUST .		120.00	30.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND TAIL GATE LOCK .		750.00	500.00
			1,880.00	1,255.00
	GRAND TOTAL		4,922.96	2,793.88
RECOMMENDED COST OF REPAIRS				2,793.88

Report Ref No. CC4/FCI21013349/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd






51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 1211J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 1211J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 1211J

RE-INSPECTION

