

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI21013350/KVCN2**Date:** 04/01/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000793
Claimant Vehicle No :	SHB9901K	Insured Vehicle No :	SMZ9532G
Date of Loss:	25/12/2021	Nature of Claim:	TP
		Claim No:	M2106006

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9901K		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H04266
Reg. Date:	16/10/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU203092287
Colour:	Metallic Pearl White/Red	Odometer:	150456 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,138.37	3,132.95	1,005.42	24.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	660.00	4,440.00	87.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,238.37	3,792.95	5,445.42	58.94
+ GST 7.00/7.00% (S\$)	646.69	265.51	381.18	58.94
Nett Amount (S\$)	9,885.06	4,058.46	5,826.60	58.94

INSPECTION

Date of Assignment:	31/12/2021	
Date Inspected:	28/12/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2022)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB9901K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER,FRONT BUMPER	Bent	521.00 FL	-	*521.00 FL
2	1		*REINFORCEMENT SUB-ASSY,FRONT BUMPER	Repair	716.60 FL	-	*- FL
3	1		*ABSORBER,FRONT BUMPER ENERGY	Serviceable	80.20 FL	-	*- FL
4	1		*BRACKET,FRONT BUMPER SIDE,LH	Distorted	59.30 FL	-	*59.30 FL
5	1		*UNIT ASSY,HEADLAMP,LH	Mtg Cracked	2,637.60 FL	-	*2,637.60 FL
6	1		*LAMP ASSY,FOG,LH	Serviceable	237.10 FL	-	*- FL
7	1		*GRILLE SUB-ASSY,RADIATOR	Distorted	422.50 FL	-	*422.50 FL
8	1		*GRILLE RADIATOR,LOWER NO 1	Cracked	178.60 FL	-	*178.60 FL
9	1		*EMBLEM ASSY,RADIATOR GRILLE	Necessary	105.80 FL	-	*105.80 FL
10	1		*MOULDING,FRONT BUMPER SIDE,LH	Cut	95.60 FL	-	*95.60 FL
11	1		*FRT BUMPER TOWING COVER	Missing	30.20 FL	-	*30.20 FL
12	1		*FRT BUMPER CLIP	Necessary	60.00 FS	-	*50.00 FS
13	1		*FRT BUMPER RETAINER CLIP	Not Necessary	65.00 FS	-	*- FS
14	1		*FRT NUMBER PLATE WITH MOULDING	Bent	200.00 FS	-	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,409.50	4,145.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,271.13	1,012.65
Total Parts (\$\$)	4,138.37	3,132.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,600.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	440.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO REMOVE AND REFIT OF REAR FENDER FITTINGS,ATTACHMENT AND	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (\$\$)			5,100.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >