



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 7656C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|--------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | REAR O/S TAIL-LAMP LOWER GARNISH (CONSISTENT) | DENTED / CUT | 355.60 | 228.90 |
| 1 | REAR BUMPER (CONSISTENT) | DENTED / CUT | 1,255.90 | 1,025.00 |
| 1 | REAR O/S BUMPER REFLECTOR (CONSISTENT) | SERVICEABLE | 135.60 | - |
| 1 | REAR O/S BUMPER SIDE RETAINER (CONSISTENT) | SERVICEABLE | 116.80 | - |
| | LESS 25% DISCOUNT | | -465.98 | -313.48 |
| | | | 1,397.92 | 940.42 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 20 | REAR BUMPER CLIP @\$2.00 (SN) (CONSISTENT) | NECESSARY | 40.00 | 40.00 |
| | | | 40.00 | 40.00 |
| | <u>LABOUR</u> | | | |
| | REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. | | 700.00 | 200.00 |
| | TO PUTTY AND SPRAY PAINT. | | 700.00 | 480.00 |
| | CHECK AND RECONNECT WIRING. | | 20.00 | 10.00 |
| | | | 1,420.00 | 690.00 |
| | GRAND TOTAL | | 2,857.92 | 1,670.42 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,300.00 |

Report Ref No. CS/ASM21013352/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.