



LE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)
	Reg No/Reg Date	SMR4949M / 10/01/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5051764
	Engine No	G4FGKH748032
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934
Description of Goods / Services					Qty Unit Price Disc% Amount
E PNT88000 RENEW FR BUMPER, FR SUPPORT, BONNET, LHF FENDER & RH FENDER @400x5					2000 4000.00
REPAIR LHF / RH F A PILLAR, LHF DOOR & RH F DOOR					2100 2800.00
E PNT98000 RESpray FR BUMPER, BONNET, LHF FENDER, RH FENDER @350x6					100.00
LHF A PILLAR, RH F A PILLAR, LHF DOOR & RH F DOOR					80.00
E PNT88000 REMOVE & REFIT AC COND & RADIATOR ASSY					400 800.00
M SUNDRY TOP UP AC GAS					400 800.00
A 54900099 REMOVE & REFIT DASHBOARD ASSY, GLOVE COMPARTMENT CENTRE CONSOLE & INSTRUMENT PNL					400 800.00
A 54900099 RENEW DRIVER AIRBAG, PASSENGER AIRBAG, AIRBAG CONTROL UNIT & AIRBAG FR SENSOR					200 400.00
A 54900099 RENEW DRIVER SEATBELT, FR PASSENGER SEATBELT & SEATBELT CATCH					200? 400.00
A 54900099 RENEW FR INTAKE MANIFOLD					30 80.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM					120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					? 1000.00
E PNT88000 CONDUCT CHASSIS ALIGNMENT - CELETTE BENCH					? 120.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment					240.00
E PNT88000 RENEW FR WINDSCREEN GLASS					280.00
M SUNDRY INSTALL FR WINDSCREEN SOLAR FILM @sate agent					80.00
M SUNDRY					

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)
	Reg No/Reg Date	SMR4949M / 10/01/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5051764
	Engine No	G4FGKH748032
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
SUPPLY WINDSCREEN SEALANT								50.00
M	SUNDRY							60 80.00
SUPPLY FR NUMBER PLATE WITH CASING								40 80.00
M	SUNDRY							30.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M	SUNDRY							
SUPPLY BODY PNL SEALANT								
M	SUNDRY							
Sundries								
M	COVER-FR BUMPER	turn			1.00	633.00	20.00	506.40
M	CAP-FRONT HOOK	sea			1.00	9.00	20.00	7.20
M	GRILLE-FRONT BUMPER	cm			1.00	262.00	20.00	209.60
M	COVER-FR BUMPER FOG LAMP, LH	cm			1.00	15.00	20.00	12.00
M	COVER-FR BUMPER FOG LAMP, RH	cm			1.00	15.00	20.00	12.00
M	GRILLE ASSY-RADIATOR	cm			1.00	328.00	20.00	262.40
M	GARNISH-RADIATOR GRILLE	cm			1.00	38.00	20.00	30.40
M	LAMP ASSY-FRONT FOG, LH	sea			1.00	303.00	20.00	242.40
M	LAMP ASSY-FRONT FOG, RH	?			1.00	303.00	20.00	242.40
M	MOULDING-FRONT BUMPER, LH	?			1.00	36.00	20.00	28.80
M	MOULDING-FRONT BUMPER, RH	?			1.00	36.00	20.00	28.80
M	LAMP ASSY-SIDE REPEATER, RH	cm			1.00	143.00	20.00	114.40
M	LAMP ASSY-SIDE REPEATER, LH	?			1.00	143.00	20.00	114.40
M	AIR DUCT-FR BUMPER, LH	sea			1.00	14.00	20.00	11.20
M	AIR DUCT-FR BUMPER, RH	sea			1.00	14.00	20.00	11.20
M	ABSORBER-FRONT BUMPER ENERGY	cm			1.00	84.00	20.00	67.20
M	STIFFNER-FR BPR LWR	st			1.00	114.00	20.00	91.20
M	BRACKET-FR BUMPER UPR SIDE MTG	sea			1.00	22.00	20.00	17.60
M	BRACKET-FR BUMPER UPR SIDE MTG	sea			1.00	22.00	20.00	17.60
M	ORNAMENT-KIA NO.115	na			1.00	32.00	20.00	25.60
M	BEAM COMPLETE-FR BUMPER	st			1.00	497.00	20.00	397.60
M	CARRIER ASSY-FRONT END MODULE	cm			1.00	675.00	20.00	540.00
M	PANEL ASSY-HOOD	st			1.00	1502.00	20.00	1201.60
M	HINGE ASSY-HOOD, LH	st			1.00	43.00	20.00	34.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



LE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)
	Reg No/Reg Date	SMR4949M / 10/01/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5051764
	Engine No	G4FGKH748032
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M HINGE ASSY-HOOD,RH <i>bt</i>		1.00	43.00	20.00	34.40
M PAD-HOOD INSULATING <i>de</i>		1.00	156.00	20.00	124.80
M CLIP-HOOD INSULATING-PAD MTG <i>an</i>		13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD <i>bt</i>		1.00	103.00	20.00	82.40
M LAMP ASSY-HEAD,LH <i>ca</i>		1.00	1219.00	20.00	975.20
M LAMP ASSY-HEAD,RH <i>ca</i>		1.00	1219.00	20.00	975.20
M PANEL-FENDER,LH <i>bt</i>		1.00	430.00	20.00	344.00
M PANEL-FENDER,RH <i>rep</i>		1.00	430.00	20.00	344.00
M GUARD ASSY-FRONT WHEEL,LH <i>?</i>		1.00	95.00	20.00	76.00
M GUARD ASSY-FRONT WHEEL,RH <i>ca</i>		1.00	95.00	20.00	76.00
M RESERVOIR & PUMP ASSY-WASHER <i>?</i>		1.00	146.00	20.00	116.80
M DUCT-EXTENSION <i>?</i>		1.00	5.00	20.00	4.00
M SHIELD-AIR INTAKE <i>?</i>		1.00	9.00	20.00	7.20
M DUCT ASSY-AIR <i>?</i>		1.00	55.00	20.00	44.00
M CLEANER ASSY-AIR <i>ca</i>		1.00	174.00	20.00	139.20
M PANEL ASSY-UNDER COVER <i>ca</i>		1.00	117.00	20.00	93.60
M CONDENSER ASSY-COOLER <i>bt</i>		1.00	687.00	20.00	549.60
M GUARD-AIR,LH <i>sc</i>		1.00	28.00	20.00	22.40
M GUARD-AIR,RH <i>sc</i>		1.00	28.00	20.00	22.40
M RADIATOR ASSY <i>bt</i>		1.00	646.00	20.00	516.80
M BLOWER ASSY <i>?</i>		1.00	656.00	20.00	524.80
M FILLER NECK ASSY-RADIATOR <i>ca</i>		1.00	28.00	20.00	22.40
M MANIFOLD ASSY-INTAKE <i>?</i>		1.00	906.00	20.00	724.80
M MOULDING-WINDSHIELD GLASS <i>an</i>		1.00	56.00	20.00	44.80
M COVER ASSY-COWL TOP <i>?</i>		1.00	247.00	20.00	197.60
M COVER-AFTER SERIVCE,LH <i>?</i>		1.00	11.00	20.00	8.80
M COVER-AFTER SERIVCE,RH <i>?</i>		1.00	11.00	20.00	8.80
M S/BELT ASSY-FR LH <i>act</i>		1.00	315.00	20.00	252.00
M S/BELT ASSY-FR RH <i>act</i>		1.00	317.00	20.00	253.60
M BUCKLE ASSY-FR S/BELT,LH <i>X</i>		1.00	179.00	20.00	143.20
M BUCKLE ASSY-FR S/BELT,RH <i>X</i>		1.00	114.00	20.00	91.20
M CRASH PAD ASSY-MAIN <i>?</i>		1.00	1279.00	20.00	1023.20
M AIR BAG ASSY-PASSENGER <i>act</i>		1.00	1275.00	20.00	1020.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

o Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)
	Reg No/Reg Date	SMR4949M / 10/01/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5051764
	Engine No	G4FGKH748032
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	MODULE ASSY-STRG WHEEL AIR BAG	1.00	922.00	20.00	737.60
M	CONTACT ASSY-CLOCK SPRING	1.00	253.00	20.00	202.40
M	SENSOR ASSY-A TYPE CRASH	2.00	54.00	20.00	86.40
M	MODULE ASSY-AIR BAG CONTROL	1.00	1025.00	20.00	820.00
M	BRACKET, IU ADHESIVE	1.00	26.00	00.00	26.00
M	COOLANT (4L)	1.00	26.00	23.00	20.02

Estimate

SURVEYOR NAME: Rasul - 4p 90010068SURVEYOR SIGNATURE: [Signature]DATE: 03/01/22 @ 1300REMARKS: 12 daysEXCESS: TBA / REVERTResum before paint

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Nett	26,532.42
7% GST on	1857.27
Total Payable	28,389.69

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.