

## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

Movement that inspires

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

No : 199405410K

## **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/TOH YING HUI ELAINE			
	Reg No/Reg Date	SMM8843J / 18/07/201			
	Date In/Mileage	31/12/2021/ 0			
	Chassis No	KNAF3416MK5047586			
	Engine No	G4FGKH741973			
	Make/Model	KIA/CERATO 1.6 A EX G333			
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator	3 12 15 16 1	WIP No	450	THE RESIDENCE
LAX00000	Credit	//	BLK	282 / Kevin Leon	g	44940		
		Description of Good	s / Service	S , Land Land Hamilton	Qty	Unit Price	Disc%	Amount/
REPLACE I REPAIR ON	RT BUMPE	B, SUPPORT, BONNET,	FRT LH F	ENDER & AFFECTED ARE	A @ 400	74	14	1600 2400.00
PNT98000		1 1	1	/		,		/1750.00
PAINT WOR	K ON FRT	BUMPER, BONNET, FRI	LH DOOR	& BOTH FRT FENDER	23,507	\$		71750.00
PN188000					_ / - / -	- 100.00		_120.00
REMOVE &	REPLACE	RADIATOR, CONDENSER						1
1 SUNDRY	ATROOM	040						/80.00
TO TOP UP SUNDRY	AIKCON	GAS						, ,
Charles and the second	SEAL ANT	ON AFFECTED AREA	100	-				60 88.0
SUNDRY		ON THE COLD AREA	77	ima	几一			on /
PERFORM R	UST PREVE	ENTION   C	211	1110019	17/0			120.0
54900099		70	5)(4	11111110	11/10	7		-20.0
CHECK WIR	ING & CHA	ASSIS ELECTRICAL SYS	TEM		0			/30.0
10028901								/120.0
TO CARRY (	DUT DIAGN	NOSTIC CHECK ON ELEC	TRONIC CO	NTROL SYSTEM				/120.0
SUNDRY TO SUPPLY	EDT NUMB	ER PLATE WITH FRAME	11/					/50.0
SUNDRY	FKI NUMB	ER PLATE WITH FRAME	M					4
SUNDRIES								30 58.0
LAMP ASSY-	HEAD I HC	m						
LAMP ASSY-	HEAD RH	7 X12			1.00	1219.00		975.2
HORN ASSY-	LOW PITCH	H ? KM			1.00	1219.00		975.2
RADIATOR AS	SSY : 51				1.00		20.00	59.2
BLOWER ASSY	1 : Kun				1.00	646.00		516.8
GUARD-AIR, L	H 50	· Children Common			1.00	656.00		524.8
GUARD-AIR,	H COC	741			1.00		20.00	22.4
CONDENSER A	SSY-COOL	ER .			1.00	687.00		22.4
PANEL ASSY-	UNDER CO	VERX			1.00	117.00		549.6
	IR: 19				1.00		20.00	93.6
DUCT ASSY-A	HOOD LT				The state of the s	33.00		44.0
DUCT ASSY-A PANEL ASSY- HINGE ASSY-	H00D 57	14/			1.00	1502.00	20.00	1201.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

No : 199405410K

## **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/TOH YING HUI ELAINE		
	Reg No/Reg Date	SMM8843J / 18/07/201		
	Date In/Mileage	31/12/2021/ 0		
	Chassis No	KNAF3416MK5047586		
	Engine No	G4FGKH741973		
	Make/Model	KIA/CERATO 1.6 A EX G333		
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK		

Account No	Terms	Date/Time Pr	rinted	CSE	Ope	rator	ALC: NO	WIP No	4	
LAX00000	Credit	31/12/2021/	13:18	BLK	282	/ Kevin Leong		44940		
2010	MAGE AND	Description	of Good	s / Services	BY TO	Shaway 5	Qty	Unit Price	Disc%	Amount
M HINGE AS	SY-HOOD, L	H 59					1.00		20.00	34.40
M PANEL-FE							1.00	430.00		344.00
PANEL-FEI	NDER, RH F	yar	/				1.00	430.00	THE RESIDENCE OF THE PARTY OF T	344.0
1 CARRIER / 1 BEAM COM	4221-FKO	T END MODULE	CIA -				1.00	675.00	SUPPOACUSTOCAGE	540.0
PAD-HOOD		BUMPER 7. XA	"				1.00	497.00	100000000000000000000000000000000000000	397.6
		WHEEL, LH ? X	'n				1.00	156.00	University of the Control of the Con	124.8
COVER-FR							1.00		20.00	76.0
		ER? KAA					1.00	633.00	THE RESERVE OF THE PARTY OF THE	506.4
GRILLE AS			N. C.				1.00	262.00		209.6
		GRILLE ?	$\leftarrow$				1.00	328.00		262.4
		MPER, LH ?			in	2	3.00		20.00	30.4
		R, LH ? XM		271	110	101501	1.60	The state of the s	20.00	28.8 11.2
		MPER ENERGY	MAT	O)[L]		1111011	16.60		20.00	67.2
STIFFNER-	FR BPR L	WR X An	The state of				1.00	114.00	ALL SANCES CONTRACTOR IN	91.2
BRACKET-F	R BUMPER	UPR SIDE MT	: XA	2			1.00		20.00	17.6
BRACKET-F	R BUMPER	UPR SIDE MTO	3 ? X	11			1.00		20.00	17.6
ORNAMENT-	KIA NO.1	15 Mm/					1.00		20.00	25.6
		S D	URVEYO ATE:C	OR NAME:	8 d	40 ays	LKK the l • To i • Par • Thi • No • Sup is so	plementary item	ne following after spray of part(s) during to confide t	ng: painting ing resurvey irmation
				٦	Miles		Signa:		dici	

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

13,854.36

Total Payable