

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22000008/AQCN2**Date:** 23/03/2022**REFERENCE**

Insured/Claimant: NG KIAN TECK, BENLY (HUANG JIANDE, BENLY) Policy No: 1800065363-03

Date of Loss: 28/12/2021

Nature of Claim: OD

Claim No: 3740190402SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKM8171M</b>	Engine No:	CHZ940609
Make & Model:	AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A)	Chassis No:	WAUZZZ8V9J1067268
Reg. Date:	18/06/2018 (Man. Year: 2018)	Odometer:	68816 km
Colour:	Black		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$87,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	18,777.00	2,161.12	16,615.88	88.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,652.00	1,242.00	3,410.00	73.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,429.00</b>	<b>3,403.12</b>	<b>20,025.88</b>	<b>85.47</b>
<b>- Excess (S\$)</b>	300.00	300.00	0.00	0.00
<b>(S\$)</b>	23,129.00	3,103.12	20,025.88	86.58
<b>+ GST 7.00/7.00% (S\$)</b>	1,619.03	217.22	1,401.81	86.58
<b>Nett Amount (S\$)</b>	<b>24,748.03</b>	<b>3,320.34</b>	<b>21,427.69</b>	<b>86.58</b>

**INSPECTION**

Date of Assignment: 03/01/2022

Date Inspected: 31/12/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,987.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	78.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	160.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	536.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	594.00 FS	*- FS
7	2		*FRONT BUMPER TRIM COVER-LH/RH	Not Necessary	326.00 FS	*- FS
8	2		*FRONT BUMPER ADAPTER-LH/RH	Not Necessary	76.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	189.00 FS	*- FS
12	1		*FRONT BUMPER SIDE REINFORCEMENT	Dented	795.00 FS	*636.00 FS
13	1		*FRONT BUMPER TOP COVER	Cut	122.00 FS	*97.20 FS
14	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	376.00 FS	*- FS
15	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
16	1		*CAUTION STICKER	Necessary	14.00 FS	*12.40 FS
17	2		*HEADLIGHT	Not Necessary	10,910.00 FS	*- FS
18	2		*LIFT CYLINDER-LH/RH	Not Necessary	284.00 FS	*- FS
19	1		*LIFT CYLINDER HOSE	Not Necessary	68.00 FS	*- FS
20	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	50.00 FS	*- FS
21	1		*RADIATOR SEAL OUTER-RH	Not Necessary	8.00 FS	*- FS
22	1		*RADIATOR AIR GUIDE-UPPER CENTER	Not Necessary	12.00 FS	*- FS
23	1		*RADIATOR BRACKET	Necessary	19.00 FS	*16.32 FS
24	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
25	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
26	1		*BONNET CATCH HOOK - LOWER	Bent	71.00 FS	*56.32 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (S\$)

18,777.00

2,161.12

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT.TO REPAIR BONNET.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,652.00</b>	<b>1,242.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >