

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22000009/ATCE2

**Date:** 29/03/2022

### REFERENCE

Insured/Claimant: PUNG YONG HIN (FENG RONGXING)  
Date of Loss: 28/12/2021

Policy No: 1700074799  
Nature of Claim: OD Claim No: 8915075148SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT7852P**  
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN041444  
Reg. Date: 10/11/2017 (Man. Year: 2017) Chassis No: WAUZZZF41HA181818  
Colour: White Odometer: 69112 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$97,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,945.00	4,430.16	21,514.84	82.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,432.00	3,182.00	8,250.00	72.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>37,377.00</b>	<b>7,612.16</b>	<b>29,764.84</b>	<b>79.63</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>37,077.00</b>	<b>7,312.16</b>	<b>29,764.84</b>	<b>80.28</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,595.39</b>	<b>511.85</b>	<b>2,083.54</b>	<b>80.28</b>
<b>Nett Amount (S\$)</b>	<b>39,672.39</b>	<b>7,824.01</b>	<b>31,848.38</b>	<b>80.28</b>

### INSPECTION

Date of Assignment: 03/01/2022

Date Inspected: 31/12/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,111.00 FS	*1,688.80 FS
2	1		*FRONT BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	196.00 FS	*156.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	210.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	126.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,152.00 FS	*921.60 FS
8	2		*FRONT AIR GUIDE GRILLE - LH / RH	Not Necessary	270.00 FS	*- FS
9	1		*FRONT FOAM FILLER PIECE	Cracked	124.00 FS	*99.20 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	845.00 FS	*675.60 FS
11	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	36.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	38.00 FS	*- FS
13	2		*FRONT REINFORCEMENT BEAM BRACKET - LH / RH	Not Necessary	456.00 FS	*364.00 FS
14	1		*FRONT BUMPER COVER	Cracked	127.00 FS	*101.60 FS
15	1		*SIGN CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
16	1		*AIR CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS
17	1		*FRONT LOCK CARRIER BRACKET	Cracked	137.00 FS	*109.60 FS
18	2		*FRONT LOCK CARRIER SUPPORT - LH / RH	Cracked	58.00 FS	*44.96 FS
19	2		*FRONT HORN - LH / RH	Not Necessary	252.00 FS	*- FS
20	2		*FRONT HORN BRACKET - LH / RH	Not Necessary	58.00 FS	*- FS
21	2		*LED HEADLIGHT - LH / RH	Not Necessary	15,386.00 FS	*- FS
22	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - LH	Not Necessary	210.00 FS	*- FS
23	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - RH	Not Necessary	210.00 FS	*- FS
24	1		*CORRUGATED PIPE FOR HEADLIGHT WASHER SYSTEM	Not Necessary	93.00 FS	*- FS
25	1		*FRONT LOCK CARRIER	Not Necessary	1,016.00 FS	*- FS
26	2		*RADIATOR SUPPORT BRACKET - LH / RH	Cracked	76.00 FS	*60.64 FS
27	1		*A/C CONDENSER	Not Necessary	622.00 FS	*- FS
28	1		*A/C CONDENSER BRACKET	Necessary	19.00 FS	*14.56 FS
29	1		*RADIATOR	Not Necessary	655.00 FS	*- FS
30	1		*ADDITIONAL RADIATOR	Not Necessary	511.00 FS	*- FS
31	6		*RADIATOR COOLANT	Not Necessary	266.00 FS	*- FS
32	2		*RADIATOR AIR GUIDE LH / RH	Torn	56.00 FS	*44.64 FS
33	2		*RADIATOR INNER AIR GUIDE LH / RH	Torn	24.00 FS	*18.88 FS
34	1		*RADIATOR LOWER AIR GUIDE	Not Necessary	22.00 FS	*- FS
35	1		*RADIATOR CENTRE AIR GUIDE	Not Necessary	16.00 FS	*- FS
36	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
37	1		*SUNDRIES	Necessary	350.00 FS	*2.56 FS
38	1		*BONNET BOWDEN CABLE	Damaged	64.00 FS	*50.56 FS

(Supplementary)

F=Franchise part. S=SpcNett.

Total Parts (S\$) 25,945.00 4,430.16

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM VACUUM AND REGAS	New	1,400.00	0.00
4	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER AND BONNET	New	3,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. TO REPAIR BONNET AND BOTH FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,500.00	750.00
7	TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF FRONT REINFORCEMENT BEAM BRACKET (Supplementary)	New	780.00	780.00
<b>Gross Labour Cost (S\$)</b>			<b>11,432.00</b>	<b>3,182.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >