

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG22000014/GVF3E2

Date: 12/01/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993564
Claimant Vehicle No : GBE6089E **Insured Vehicle No :** GBC9637P
Date of Loss: 21/12/2021 Nature of Claim: TP Claim No: 5994870751SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE6089E**
Make & Model: NISSAN CABSTAR, 2.0 (M) Engine No: ZD30346898K
Reg. Date: 28/12/2015 (Man. Year: 2015) Chassis No: JN1SC2F24Z0857989
Colour: Gold Odometer: 204438 km
Engine Capacity: 2953 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 165 R13
Front Left Side: CST 6 mm Rear Left Side: Maxxis 6 mm
Front Right Side: CST 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/01/2022
Date Inspected: 03/01/2022 Inspected At: JI Auto Services Pte Ltd (HQ)
Blk 3006 UBI ROAD 1 #01-346
Singapore 408700
Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$32,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Distorted	0.00 F	*- F
2	1		*FRT GRILLE	Broken	0.00 F	*- F
3	1		*FRT GRILLE EMBLEM	Cracked	0.00 F	*- F
4	1		*FRT PANEL	Buckled	0.00 F	*- F
5	1		*FRT PANEL EMBLEM	Distorted	0.00 F	*- F
6	2		*FRT CORNER PANEL	O/S Dented / N/S Missing	0.00 F	*- F
7	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
8	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
9	2		*FRT SIDE MIRROR (BIG) RH&LH	Cut	0.00 F	*- F
10	1		*FRT SIDE MIRROR (SMALL) RH	Cut	0.00 F	*- F
11	1		*FRT WING MIRROR STAY RH	Bent	0.00 F	*- F
12	1		*AIRCON CONDENSER	Dented	0.00 F	*- F
13	1		*AIR CON LIQUID PIPE	Bent	0.00 F	*- F
14	1		*FRT CABIN MOUNTING	Distorted	0.00 F	*- F
15	1		*FRT LH DOOR	Repair	0.00 F	*- F
16	1		*FRT DOOR FRT PILLAR LH	Repair	0.00 F	*- F
17	1		*STICKER	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)0.000.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >