

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711**Our File No:** CS/III22000016/UTF3N2**Date:** 12/01/2022**REFERENCE**

Insured/Claimant:	ANG EEK KOON	Policy No:	D19MPC0001672_02		
Date of Loss:	01/01/2022	Nature of Claim:	OD	Claim No:	MPC2022D0000039

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK8941E		
Make & Model:	BMW 216I, 1.5 (A)	Engine No:	38825142B38A15A
Reg. Date:	24/04/2018 (Man. Year: 2017)	Chassis No:	WBA2D920005K80890
Colour:	Black	Odometer:	66159 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,643.95	2,554.65	3,089.30	54.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	1,280.00	1,150.00	47.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,073.95	3,834.65	4,239.30	52.51
Approved Total (Overridden) (S\$)		3,050.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	7,473.95	2,450.00	5,023.95	67.22

INSPECTION

Date of Assignment:	03/01/2022		
Date Inspected:	03/01/2022	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2022)
Parts: M1-MPV	BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJK8941E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,086.00 FL	*1,086.00 FL
2	12		*FRONT BONNET INSULATOR CLIPS	Not Necessary	108.00 FL	*- FL
3	1		*FRONT BUMPER	Deformed/Cut	985.00 FL	*985.00 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	180.00 FL	*60.00 FL
5	1		*FRONT BUMPER LOGO EMBLEM	Serviceable	78.00 FL	*- FL
6	1		*FRONT BUMPER N/S GRILLE (WITH CHROME)	Cracked	128.00 FL	*128.00 FL
7	1		*FRONT BUMPER CENTRE LOWER AIR SCOOP GRILLE	Twisted	135.00 FL	*135.00 FL
8	1		*SET FRONT BUMPER RIVETS	Necessary	180.00 FL	*40.00 FL
9	1		*FRONT BUMPER SPONGE DAMPER	Serviceable	65.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	395.00 FL	*- FL
11	1		*FRONT NUMBER PLATE GARNISH	Deformed	85.00 FL	*85.00 FL
12	1		*SET FRONT BUMPER O/S & N/S OUTER SENSOR	Serviceable	656.00 FL	*- FL
13	1		*SET FRONT BUMPER O/S & N/S INNER SENSOR	Serviceable	656.00 FL	*- FL
14	1		*N/S HEAD LAMP ASSY	Not Necessary	976.00 FL	*- FL
15	1		*FRT O/S GRILLE	Cracked	128.00 FL	*128.00 FL
16	1		*FRONT NUMBER PLATE WITH BMW FRAME	Cracked	95.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,936.00	2,687.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	292.05	132.35
Total Parts (\$\$)	5,643.95	2,554.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	80.00	30.00
2	TO DIAGNOSE & RE-SET FRONT BUMPER SENSOR	New	150.00	50.00
3	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT NECESSARY PARTS,TO WELD,RENEW & ALIGN ABOVE PARTS	New	900.00	600.00
4	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,300.00	600.00
			Gross Labour Cost (\$)	2,430.00
				1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >