

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000017/UTY3N2**Date:** 12/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00193532000		
Claimant Vehicle No :	SJN5253L	Insured Vehicle No :	SMW9227D		
Date of Loss:	30/12/2021	Nature of Claim:	TP	Claim No:	SNM21D207715/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN5253L		Engine No:	L15B4531298
Make & Model:	HONDA HR-V, 1.5 (A)		Chassis No:	JHMRU1810GX201298
Reg. Date:	02/12/2016 (Man. Year: 2016)		Odometer:	155305 km
Colour:	White			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Yes

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,160.00	2,054.80	5,105.20	71.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,510.00	1,250.00	45.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,920.00	3,564.80	6,355.20	64.06
Approved Total (Overridden) (S\$)		2,850.00		
(S\$)	9,920.00	2,850.00	7,070.00	71.27
+ GST 7.00/7.00% (S\$)	694.40	199.50	494.90	71.27
Nett Amount (S\$)	10,614.40	3,049.50	7,564.90	71.27

INSPECTION

Date of Assignment:	04/01/2022		
Date Inspected:	03/01/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2022)
Parts: M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJN5253L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Badly Dented	1,209.60 FL	*779.20 FL
2	1		*TAILGATE LID HR-V BADGE	Necessary	66.90 FL	*66.90 FL
3	1		*TAILGATE LID INNER LOCK-STRIKER	Not Necessary	53.50 FL	*- FL
4	1		*TAILGATE LID ONNER TRIMBOARD	Deformed/Torn	194.30 FL	*180.20 FL
5	1		*TAILGATE LID CHANNEL WEATHERSTRIP	Twisted	192.50 FL	*92.30 FL
6	2		*TAILGATE LID INNER TRIM SIDE	Not Necessary	151.20 FL	*- FL
7	1		*TAILGATE LID INNER TRIM TOP	Not Necessary	75.60 FL	*- FL
8	2		*TAILGATE LID RUBBER STOPPER	Not Necessary	24.00 FL	*- FL
9	1		*TAILGATE LID INNER OPENING GARNISH HANDLE	Not Necessary	170.10 FL	*- FL
10	1		*TAILGATE LID OPENING LEVER SENSOR	Not Necessary	128.90 FL	*- FL
11	2		*REAR WINDSCREEN GLASS SIDE RUBBER SEAL	Necessary	150.00 FL	*85.00 FL
12	2		*REAR WINDSCREEN GLASS STOPPER	Not Necessary	24.00 FL	*- FL
13	2		*REAR WINDSCREEN GLASS INNER SIDE GARNISH	Not Necessary	263.20 FL	*- FL
14	1		*REAR WINDSCREEN GLASS INNER TOP GARNISH	Not Necessary	159.10 FL	*- FL
15	1		*REAR LICENCE PLATE GARNISH	Not Necessary	295.40 FL	*- FL
16	1		*TAILGATE LID GARNISH WITH H BADGE	Not Necessary	235.60 FL	*- FL
17	2		*REAR LICENCE PLATE LAMP	Not Necessary	98.20 FL	*- FL
18	2		*REAR LAMP	Not Necessary	913.60 FL	*- FL
19	1		*REAR END PANEL	Repair	585.60 FL	*- FL
20	1		*REAR END PANEL INNER TRIM	Not Necessary	179.10 FL	*- FL
21	4		*REAR END PANEL INNER TRIM CLIPS	Not Necessary	20.80 FL	*- FL
22	1		*REAR BUMPER CENTRE	Dented	721.70 FL	*535.90 FL
23	1		*REAR BUMPER REFLECTORS	O/s Cracked	288.60 FL	*144.30 FL
24	2		*REAR BUMPER TOP FASTENER SCREW	Not Necessary	9.60 FL	*- FL
25	2		*REAR BUMPER TOP FASTENER SCREW SPACER	Not Necessary	9.60 FL	*- FL
26	1		*SET REAR BUMPER FASTENER CLIPS	Necessary	41.60 FL	*30.00 FL
27	2		*REAR BUMPER SIDE	Repair	195.00 FL	*- FL
28	2		*REAR BUMPER SIDE FASTENER SCREW	Not Necessary	8.80 FL	*- FL
29	2		*REAR BUMPER SIDE RETAINER	Not Necessary	136.60 FL	*- FL
30	1		*REAR BUMPER LOWER SPLASHIELD COVER	Twisted	274.70 FL	*274.70 FL
31	1		*SET REAR BUMPER LOWER SPLASHIELD COVER LOCK CLIP	Necessary	41.60 FL	*30.00 FL
32	1		*REAR BUZZLE ASSY	Not Necessary	356.00 FL	*- FL
33	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	150.00 FS	*40.00 FS
35	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
36	1		*REAR REVERSE CAMERA LEN	Not Necessary	380.00 FS	*- FS
37	1		*REAR BUMPER PARKING SENSOR	Shorted	380.00 FS	*200.00 FS
38	1		*REAR LUGGAGE FLOOR INSULATOR	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,615.00	2,498.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,455.00	443.70
Total Parts (\$\$)	7,160.00	2,054.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	200.00	40.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	50.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
5	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	60.00	0.00
6	TO TRANSFER OF TAILGATE FITTINGS, FIXTURE AND PERFORM WATERSEEPAGE TEST	New	120.00	80.00
7	TO REMOVE AND REINSTALL REVERSE CAMERA	New	80.00	0.00
8	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,000.00	600.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	600.00
			Gross Labour Cost (\$)	2,760.00
				1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >