



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 3999H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT WINDSCREEN MOULDING	NECESSARY	154.50	154.50
1	FRONT PANEL	DENTED	1,352.50	1,227.00
2	FRONT CORNER PANELS @\$535.50	O/S DENTED	1,071.00	477.00
2	FRONT HEADLAMPS @\$373.00	O/S CRACKED	746.00	373.00
1	FRONT GRILLE	CUT	504.00	504.00
1	FRONT BUMPER	TO REPAIR SEE LABOUR	892.70	-
	LESS 30% DISCOUNT		-1,416.21	-820.65
			3,304.49	1,914.85
	<b><u>NETT ITEMS</u></b>			
2	FRONT BUMPER SIDE RETAINERS @\$17.50 (N)	NECESSARY	35.00	35.00
	LESS 10% DISCOUNT		-3.50	-3.50
			31.50	31.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	BENT	60.00	40.00
			60.00	40.00
	<b><u>LABOUR</u></b>			
	TO REMOVE AND REFIT HEADLAMPS.		50.00	20.00
	TO REMOVE AND REFIT DASHBOARD.	NOT NECESSARY	400.00	-
	TO REMOVE AND REFIT WINDSCREEN GLASS.		200.00	120.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		1,100.00	600.00
	SPRAY PAINTING.		1,100.00	600.00
	TO UNDERSEAL.		150.00	30.00
			3,000.00	1,370.00
	<b>GRAND TOTAL</b>		<b>6,395.99</b>	<b>3,356.35</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00
---	--	--	----------

Report Ref No. CS/UOI22000023/Vvf3e2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.