

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000029/UTY3N2**Date:** 10/03/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00088022100		
Claimant Vehicle No :	SMQ5682E	Insured Vehicle No :	SCW30G		
Date of Loss:	30/12/2021	Nature of Claim:	TP	Claim No:	SNM22D200002/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ5682E	Engine No:	G4FGKH739816
Make & Model:	KIA CERATO, 1.6 EX (A)	Chassis No:	KNAF3416ML5059930
Reg. Date:	25/11/2019 (Man. Year: 2019)	Odometer:	28465 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Kumho 8 mm	Rear Left Side:	Kumho 8 mm
Front Right Side:	Kumho 8 mm	Rear Right Side:	Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,565.70	8,976.30	8,589.40	48.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,030.00	2,920.00	2,110.00	41.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,595.70	11,896.30	10,699.40	47.35
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	22,595.70	9,500.00	13,095.70	57.96
+ GST 7.00/7.00% (S\$)	1,581.70	665.00	916.70	57.96
Nett Amount (S\$)	24,177.40	10,165.00	14,012.40	57.96

INSPECTION

Date of Assignment:	04/01/2022	
Date Inspected:	31/12/2021 Inspected At:	Automobile Integrated Management Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing) Singapore 415933
Estimated Period of Repair:	9.0 days	

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Mar 2022)
Parts: 143	KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMQ5682E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented/Bent	1,297.00 FL	*1,297.00 FL
2	1		*REAR BOOT LOGO	Necessary	85.00 FL	*45.00 FL
3	1		*REAR BOOT EMBLEM CERATO	Necessary	89.00 FL	*42.00 FL
4	1		*REAR BOOT LAMPS-L/R	O/s Cracked	1,216.00 FL	*608.00 FL
5	1		*REAR BOOT REFLECTOR-CTR	Not Necessary	690.00 FL	*- FL
6	1		*REAR BOOT INNER LOCK	Bent	285.00 FL	*112.00 FL
7	1		*REAR BOOT INNER TRIM	Deformed/Torn	265.00 FL	*202.00 FL
8	10		*REAR BOOT INNER TRIM CLIPS	Necessary	45.00 FL	*45.00 FL
9	1		*REAR BOOT LOCK STRIKER	Not Necessary	42.00 FL	*- FL
10	1		*REAR BOOT W/STRIP	Twisted	146.00 FL	*136.00 FL
11	2		*REAR BOOT HINGES-L/R	Not Necessary	230.00 FL	*- FL
12	2		*REAR BOOT STOPPERS	Not Necessary	24.00 FL	*- FL
13	1		*REAR BUMPER	Distorted	688.00 FL	*688.00 FL
14	1		*REAR BUMPER DIFFUSER	Distorted	326.00 FL	*326.00 FL
15	1		*REAR BUMPER LAMPS-L/R	N/s Cracked	378.00 FL	*189.00 FL
16	2		*REAR BUMPER LAMP GARNISHES-L/R	Cut	224.00 FL	*224.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Cracked	465.00 FL	*318.00 FL
18	2		*REAR BUMPER REINFORCEMENT STAYS-L/R	Bent	230.00 FL	*230.00 FL
19	2		*REAR BUMPER SIDE RETAINERS-L/R	Bent	110.00 FL	*110.00 FL
20	1		*REAR BUMPER UNDERCOVER	Not Necessary	122.00 FL	*- FL
21	1		*REAR END PANEL	Badly Dented	473.00 FL	*473.00 FL
22	1		*REAR END PANEL GARNISH	Twisted	192.00 FL	*192.00 FL
23	1		*REAR EXHAUST SILENCER	Not Necessary	675.00 FL	*- FL
24	1		*REAR EXHAUST INSULATOR	Not Necessary	89.00 FL	*- FL
25	2		*REAR EXHAUST MOUNTINGS	Not Necessary	36.00 FL	*- FL
26	1		*REAR FLOOR BOARD	Warped	765.00 FL	*511.00 FL
27	2		*REAR FENDERS-L/R	Repair	1,790.00 FL	*- FL
28	2		*REAR FENDER INNER TRIMS-L/R	Not Necessary	630.00 FL	*- FL
29	2		*REAR FENDER INNER SHIELDS-L/R	Not Necessary	112.00 FL	*- FL
30	1		*REAR SMART KEYLESS ANTENNA	Shorted	189.00 FL	*189.00 FL
31	2		*REAR TAILLAMPS-L/R	Cracked	1,350.00 FL	*1,350.00 FL
32	2		*REAR TAILLAMP PANELS-L/R	Repair	270.00 FL	*- FL
33	1		*FRONT WINDSCREEN MOULDING	Not Necessary	112.00 FL	*- FL
34	1		*FRONT BUMPER	Dented/Deformed	698.00 FL	*698.00 FL
35	1		*FRONT BUMPER LOWER EXTENSION	Bent	388.00 FL	*388.00 FL
36	1		*FRONT BUMPER LOWER GRILLE	Deformed	155.20 FL	*155.20 FL
37	2		*FRONT BUMPER FOG LAMPS-L/R	Not Necessary	583.00 FL	*- FL
38	1		*FRONT BUMPER LOGO	Necessary	85.00 FL	*85.00 FL
39	1		*FRONT BUMPER SPONGE	Torn	113.60 FL	*113.60 FL
40	1		*FRONT BUMPER REINFORCEMENT	Bent	441.50 FL	*441.50 FL
41	2		*FRONT BUMPER SIDE RETAINERS-L/R	Necessary	77.20 FL	*77.20 FL
42	1		*FRONT GRILLE ASSY	Cracked	361.50 FL	*361.50 FL
43	2		*FRONT HEADLAMPS-L/R	Not Necessary	1,730.00 FL	*- FL
44	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
45	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
46	1		*REAR REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR NO PLATE	Not Necessary	60.00 FS	*- FS
48	1		*SET REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
50	1		*SET FRONT NO PLATE	Bent	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,393.00	9,937.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,827.30	960.70
Total Parts (\$\$)	17,565.70	8,976.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT & REAR ELECTRICAL WIRING	New	100.00	30.00
2	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	80.00
3	TO REMOVE,REFIX REAR EXHAUST SYSTEMS	New	100.00	0.00
4	TO RESPRAY UNDERCOATING	New	150.00	60.00
5	TO REMOVE,REFIX REAR WINDSCREEN	New	180.00	0.00
6	TO REMOVE,REFIX REAR REVERSE SENSOR/CAMERA	New	80.00	50.00
7	TO RESPRAY PAINTING AND ETC	New	1,800.00	1,500.00
8	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS	New	2,500.00	1,200.00
			Gross Labour Cost (\$)	5,030.00
				2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >