6/14/22, 11:30 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG22000034/TEA3Q2

14/06/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210121947 **Claimant Vehicle**

SHC801U Insured Vehicle No: **SNC2869R** No:

Date of Loss: 31/12/2021 Nature of Claim: TP Claim No: 3483886244SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC801U**

Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A) G4LEKU393123 Engine No:

Reg. Date: 16/01/2020 (Man. Year: 2019) Chassis No: KMHC851CVLU184164

Colour: Odometer: 212294 km Yellow

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		981.12	72.60	908.52	92.60
Miscellaneous Items		0.00	0.00	0.00	
Labour		820.00	630.00	190.00	23.17
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	1,801.12	702.60	1,098.52	60.99
	+ GST 7.00/7.00% (S\$)	126.08	49.18	76.90	60.99
	Nett Amount (S\$)	1,927.20	751.78	1,175.42	60.99
	+ Loss of Use (2.5 x	S\$50.00/day) (S\$)	125.00		
	+ Car Rental (2.5 x S	\$129.47/day) (S\$)	323.68		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	1,202.46		
	Global Sui	m Settlement (S\$)	1,200.00		

INSPECTION

Date of Assignment: 03/01/2022

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 03/01/2022 Inspected At:

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

MOHD TAUFIKH BIN HAMID Adjuster: Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER CENTRE MOULDING ASSY	Repair	451.25 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REVERSE SENSORS	Not Necessary	180.00 FS	*-FS
5	1		*REAR NO PLATE WITH TRIM COVER	Cracked	55.00 FS	*55.00 FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	-		
				Sub Total (S\$)	1,167.65	77.00
			- List Item Discount on L Iten	ns 20.00/20.00% (S\$)	186.53	4.40
				Total Parts (S\$)	981.12	72.60
			Report was unsubmitted during this	print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
		Gross Labour Cost (S\$)	820.00	630.00
	Report was	s unsubmitted during this print-out.		

< END OF ESTIMATES >