455. REC. BY: Tayph - REF: 44/1944 22	0000 34 71093.
ASS	SIGNMENT
rom: Date:	Veh No: SHC801 U. Yr Regn: 2020 / Jun.
stimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Tax) / Prime Mover /
D/TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
o Inspect Vehicle No:	Make: Hyndeplonia, c.c 15to.
	Colour /closs A/C: Insured / Std / NI / NA
· ·	Sp.Reading 712294 T/Radio: Insured / Std / NI / NA
sured:	Eng/Np:
laliar Na	C/No: Wm H (851CV * L 4184/64
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
tum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: (Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 195/65/KIS
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	<u> </u>
repair at the time of inspection.	TOYO/YOKO or Westah.
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 0 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. C mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 3/1/22
Lum Sum: % 3 Val.: Yes or No	Survey held at Comfort Coggs
WY /	Des. of Damages : Frt / Rear / O/S / N/S / U/S / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / O	OUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
1	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add	
	: Interview (\$) Photos
Repert Format :	:Tech. Invs (\$) Others
Lump Sum / LB.A: (F	: Westend (%
	TOTAL
· · · · · · · · · · · · · · · · · · ·	

COMFORTDELGRO ENGINEERING PTE ↓TD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE:

3-Jan-22

MODEL:

Hyundai loniq

VEHICLE NO.: SHC 801U - CityCab

INSURANCE: AIG ASIA (P)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1	K	> \$459.40
	Rear Bumper Centre Moulding Assy	1		\$451.25
	Rear Bumper Clips	10	\$2.20 1	\$22.00
	SUB TOTAL			\$932.65
	LESS 20%			\$186.53
	DISCOUNTED TOTAL			\$746.12
	Reverse Sensors	1		7 \$180.00
	Rear No.Plate With Trim Cover	1		\$55.00
	S/NETT TOTAL			\$235.00
	SPARE PARTS TOTAL			\$981.12
	Labour Charge		35	\$400.00
	Panel Beating		25	
	Spray Painting Charge Remove/Refix Reverse Sensor		3	\$120.00
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL			\$1,801.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Detell



irned to Service Reception upon collection

omfortDelGro Engineering Pte Ltd

Date

Date/Time: 03.01.2022 12:10 Page : 1 JOB CARD Sales Order: 4158730 am: ARC Repair TP(CFSO)1 JC NO305499963 **OMER** REGN NO. 801U MILEAGE CITYCAB PTE LTD FUEL 7010070 HYUNDAI OMERNO. 383 SIN MING DRIVE 03.01.2022 08:20 Singapore SINGAPORE 575717 IONIQ(G3) 65551188 (R) OF MANU. 16.01.2020 TARGET DATE ASSIS CODE KMHC851CVLU184164 COMPLETION DATE/TIME: DUNT CARD NO. JOB DESCRIPTION cident Date: 31.12.2021 TURE: 3P 31.12.2021 NO LABOR CODE DESCRIPTION 0010 PR PANEL BEATING-SHC 801U KED & PASSED OUT BY: SERVICE ADVISOR CUSTOMER'S SIGNATURE adgement Slip Exit Pass Vehicle No.: SHC 801U LIMTS SHC 801U Service Advisor Signature/Date Name of Service Advisor

To be kept by Security Guard