

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000035/R1VY3N2**Date:** 27/01/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00147502103

**Claimant Vehicle
No :** YN1888D**Insured Vehicle
No :** GBE4431M

Date of Loss: 30/12/2021

Nature of Claim: TP

Claim
No: SNM22D200004/C02/CSC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **YN1888D**

Make & Model: MITSUBISHI FE83BE6SRDEA, 3.0 D (A)

Engine No: 4M42A70932

Reg. Date: 11/02/2009 (Man. Year: 2008)

Chassis No: FE83BEA11238

Colour: White

Odometer: 408556 km

Engine Capacity: 2977 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00R16C

Rear Tyre Size:

7.00R16C (D)

Front Left Side: Neuton 7 mm

Rear Left Side:

Neuton 7/7 mm

Front Right Side: Neuton 7 mm

Rear Right Side:

Neuton 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,979.30	4,322.00	1,657.30	27.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,040.00	2,020.00	1,020.00	33.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,019.30	6,342.00	2,677.30	29.68
Approved Total (Overridden) (\$\$)		5,050.00		
(\$\$)	9,019.30	5,050.00	3,969.30	44.01
+ GST 7.00/7.00% (\$\$)	631.35	353.50	277.85	44.01
Nett Amount (\$\$)	9,650.65	5,403.50	4,247.15	44.01

INSPECTION

Date of Assignment: 05/01/2022

Date Inspected: 06/01/2022 Inspected At:

Wah Hong Motors & Credit Pte Ltd (HQ)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jan 2022)	
Parts:	N/A	MITSUBISHI FE83BE6SRDEA 3.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN1888D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Bent	1,636.00 FL	*1,636.00 FL
2	1		*CENTER GRILLE	Cracked	599.00 FL	*599.00 FL
3	1		*CENTER GRILLE LOGO BADGE	Necessary	85.00 FL	*85.00 FL
4	1		*CENTER GRILLE EMBLEM FUSO	Necessary	160.00 FL	*160.00 FL
5	1		*FRONT BUMPER	Bent	986.00 FL	*986.00 FL
6	2		*FRONT BUMPER SIDE BRACKET LH/RH	Bent	410.00 FL	*410.00 FL
7	1		*SIGNAL LAMP RH	Not Necessary	211.00 FL	*- FL
8	1		*TAIL GATE STICKER FUSO	Necessary	180.00 FL	*180.00 FL
9	1		*AIRCON PIPE H	Bent	380.00 FL	*380.00 FL
10	1		*AIRCON PIPE L	Bent	380.00 FL	*380.00 FL
11	2		*FRONT DOOR RH/LH (NPA)	Repair	0.00 FL	*- FL
12	1		*TAIL GATE (NPA)	Repair	0.00 FL	*- FL
13	1		*FRONT CAR PLATE	Bent	35.00 FS	*35.00 FS
14	1		*REAR TAIL GATE STICKER 60KM/H	Necessary	20.00 FS	*10.00 FS
15	1		*REAR TAIL GATE STICKER 22 PAX	Necessary	20.00 FS	*10.00 FS
16	1		*TAIL GATE WARNING STICKER	Necessary	100.00 FS	*50.00 FS
17	1		*REAR STEP UP METAL ASSY	Bent	500.00 FS	*200.00 FS
18	1		*REAR STEP UP METAL ASSY WARNING STICKER	Necessary	100.00 FS	*50.00 FS
19	1		*FRONT DOOR COMPANY DECAL RH/LH (2 Pcs)	Necessary (1 Pc only)	50.00 FS	*25.00 FS
20	2		*FRONT DOOR LOGO STICKER RH/LH	Necessary	200.00 FS	*100.00 FS
21	2		*FRONT DOOR WARNING STICKER RH/LH	Necessary	200.00 FS	*100.00 FS
22	1		*CENTER GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
23	1		*FRONT BUMPER WARNING STICKER	Necessary	100.00 FS	*50.00 FS
24	1		*FRONT PANEL WARNING STICKER	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **6,482.00** **5,526.00**
- List Item Discount on L Items 10.00/25.00% (\$\$) 502.70 1,204.00

Total Parts (\$\$) **5,979.30** **4,322.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	900.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,400.00	1,000.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	40.00
4	TO REMOVE AND RE-FIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK ALL ELECTRICAL & COMPONENT FOR PROPER FUNCTION	New	60.00	0.00
5	REMOVE AND REFIT AIRCON CONDENSER,RELATED PIPES AND HOSES,VACCUM AND REFILL AIRCON GAS	New	120.00	80.00
Gross Labour Cost (\$\$)			3,040.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >