



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YN1888D MITSUBISHI FUSO FE83

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front panel <i>bt</i>		1636.00	4816
1	Center grille <i>ca</i>		599.00	25%
1	Center grille logo badge <i>ne</i>		85.00	
1	Center grille emblem "Fuso" <i>ne</i>		160.00	
1	Front bumper <i>bt</i>		986.00	3612
2	Front bumper side bracket LH/RH @2*\$205 <i>bt</i>		410.00	
1	Signal lamp RH <i>Xnn</i>		211.00	X
1	Tail gate sticker "Fuso" <i>ne</i>		180.00	
1	Aircon pipe H <i>bt</i>		380.00	
1	Aircon pipe L <i>bt</i>		380.00	
2	Front door RH/LH (Repair refer to labour) <i>Repair</i>		0.00 X	
1	Tail gate (Repair refer to labour) <i>Repair</i>		0.00 X	
			5027.00	
			-10% -502.70	
			4524.30	
SPECIAL NETT ITEMS				
1	Front car plate <i>bt</i>		35.00	
1	Rear tail gate sticker 60km/h <i>ne</i>		20.00	10
1	Rear tail gate sticker 22 Pax <i>ne</i>		20.00	10
1	Tail gate warning sticker <i>ne</i>		100.00	50
1	Rear step up metal assy <i>bt</i>		500.00	200
1	Rear step up metal assy warning sticker <i>ne</i>		100.00	50
2	Front door company decal RH/LH @2*\$25 <i>ne</i>		50.00	25
2	Front door logo sticker RH/LH @2*\$100 <i>ne</i>		200.00	100
2	Front door warning sticker RH/LH @2*\$100 <i>ne</i>		200.00	100
1	Center grille clips <i>ne</i>		30.00	
1	Front bumper warning sticker <i>ne</i>		100.00	50
1	Front panel warning sticker <i>ne</i>		100.00	50
Total Parts			5979.30	710



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YN1888D MITSUBISHI FUSO FE83

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	1400.00 900
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	1000
3	To perform anti-rust treatment on affected areas	60.00	40
4	To remove and re-fix wiring system at accident damaged area and check all electrical & component for proper function	60.00	X 11
5	Remove and refit aircon condenser, related pipes and hoses, vaccum and refill aircon gas	120.00	80
Labour Total :		3040.00	
TOTAL (PARTS & LABOUR):		9019.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3612

710

2020

6342

20%

5073.60

4/5 - \$5,050

Rasul

Hp 90010068

8 days

4/5

06/01/22 @ 1640

Resurvey after repair