



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 8690U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	TORN / DEFORMED	600.50	600.50
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	683.48	-
1	REAR BUMPER SIDE RETAINER LH	NECESSARY / DAMAGED	65.10	65.10
1	TAIL LAMP LH	CRACKED	345.40	345.40
1	REAR FENDER LH	CRUSHED	1,589.00	1,589.00
1	SLIDING DOOR LH	TO REPAIR SEE LABOUR	2,451.00	-
1	TAIL LAMP PANEL LH	BENT	172.10	172.10
1	REAR DOOR HINGE LH	DAMAGED	65.80	65.80
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,758.00	-
1	REAR DOOR EMBLEM "DOBLO MAX" LH	NECESSARY	79.80	79.80
1	REAR DOOR "90 MULTIJET 2" LH	NECESSARY	64.10	64.10
1	REAR END PANEL	TO REPAIR SEE LABOUR	612.00	-
	LESS 10% DISCOUNT		-848.63	-298.18
			7,637.65	2,683.62
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	250.00	-
1	REAR FENDER SEALANT LH (SN)	SERVICEABLE	40.00	-
1	REAR DOOR STICKER 70KM/H LH (SN)	MISSING	15.00	15.00
10	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
			365.00	45.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF SLIDING DOOR LH, REAR DOOR LH AND REAR END PANEL.		765.00	700.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL. (REAR FENDER LH, SLIDING DOOR LH, REAR BUMPER, REAR DOOR LH)		850.00	800.00

Report Ref No. CS3/LPC21011726/Gvf3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY RUST PROOFING ON THE ADJACENT PANELS.	NOT NECESSARY	50.00	50.00
	CONDUCT WATER LEAK TEST FOR REAR PORTION ASSOCIATED REPAIR WORKS.		45.00	-
	REMOVE AND REFIX REAR REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING.		76.50	40.00
	WIRING AND BULB CHECKING.		36.00	30.00
			1,822.50	1,620.00
GRAND TOTAL			9,825.15	4,348.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,450.00

Report Ref No. CS3/LPC21011726/Gvf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.