

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22000048/KPA3Q2**Date:** 05/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0002998_02

Claimant Vehicle No : SMR546T **Insured Vehicle No :** YM1961E

Date of Loss: 31/12/2021 Nature of Claim: TP Claim No: MFL2022D0000044

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR546T**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR2A40742

Reg. Date: 17/12/2019 (Man. Year: 2018) Chassis No: ZYX102130684

Colour: Metallic Yellow Odometer: 110846 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17

Front Left Side: INTERTRAC 9 mm Rear Left Side: INTERTRAC 9 mm

Front Right Side: INTERTRAC 9 mm Rear Right Side: INTERTRAC 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,899.75	5,558.67	1,341.08	19.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,220.00	680.00	35.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,799.75	6,778.67	2,021.08	22.97
+ GST 7.00/7.00% (S\$)	615.98	474.51	141.47	22.97
Nett Amount (S\$)	9,415.73	7,253.18	2,162.55	22.97
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
		7,653.18		
Liabe Amount (50.00%) (S\$)		3,826.59		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,863.04		
Global Sum Settlement (S\$)		3,850.00		

INSPECTION

Date of Assignment: 03/01/2022

Date Inspected: 03/01/2022 Inspected At:

Estimated Period of Repair: 4.0 days

Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05 AMK
Autopoint
Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Feb 2022)

Parts: M1-SUV TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMR546T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Cut	1,727.00 FL	*1,727.00 FL
2	1		*FRONT BUMPER	Cracked	399.00 FL	*399.00 FL
3	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	115.00 FL	*115.00 FL
4	1		*FRONT BUMPER FOG LAMP GARNISH COVER RH	Missing	88.00 FL	*88.00 FL
5	1		*FRONT BUMPER LOWER GRILLE	Dented / Cut	505.00 FL	*359.00 FL
6	1		*FRONT GRILLE	Serviceable	173.00 FL	*- FL
7	1		*FRONT FENDER RH	Bent	826.00 FL	*826.00 FL
8	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	65.00 FL	*65.00 FL
9	1		*FRONT FENDER INNER SHIELD RH	Cracked	236.00 FL	*236.00 FL
10	1		*FRONT FENDER WHEEL ARCH GARNISH COVER RH	Missing	143.00 FL	*143.00 FL
11	1		*FRONT RIM RH	Dented	2,128.00 FL	*1,550.00 FL
12	1		*FRONT ABSORBER RH	Bent	493.00 FL	*493.00 FL
13	1		*FRONT LOWER ARM RH	Bent	760.00 FL	*497.00 FL
14	1		*FRONT KNUCKLE ARM RH	Bent	698.00 FL	*495.50 FL
15	1		*FRONT WHEEL BEARING RH	Necessary	697.00 FL	*271.40 FL
16	1		*FRONT BONNET (NPA)	Repair	0.00 FL	*- FL
17	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
18	1		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	30.00 FS	*30.00 FS
19	1		*FRONT FENDER WHEEL ARCH COVER CLIPS RH	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,163.00	7,374.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,263.25	1,816.23
Total Parts (\$\$)	6,899.75	5,558.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE REFIX REPAIR & READJUST ACCIDENT AREAS & ETC	New	700.00	400.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ,FRONT FENDER RH ,FRONT BONNET & ETC	New	700.00	600.00
3	LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH ,FRONT LOWER ARM RH ,FRONT KNUCKLE ARM RH & ETC	New	200.00	180.00
4	TO WHEEL ALIGNMENT & BALANCING	New	80.00	20.00
5	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	120.00	0.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	100.00	20.00
Gross Labour Cost (\$)			1,900.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >