

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22000053/AGA3Q2**Date:** 19/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210018298
Claimant Vehicle No :	SJA1108T	Insured Vehicle No :	SKK410L
Date of Loss:	31/12/2021	Nature of Claim:	TP
		Claim No:	1764366378SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA1108T		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Engine No:	CZC298673
Reg. Date:	16/02/2016 (Man. Year: 2015)	Chassis No:	WAUZZZ8V1G1045709
Colour:	Black	Odometer:	88567 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,686.00	1,845.60	1,840.40	49.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,872.00	1,522.00	2,350.00	60.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,558.00	3,367.60	4,190.40	55.44
+ GST 7.00/7.00% (S\$)	529.06	235.73	293.33	55.44
Nett Amount (S\$)	8,087.06	3,603.33	4,483.73	55.44
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
	Nett Liability (S\$)	3,753.33		

INSPECTION

Date of Assignment:	10/01/2022		
Date Inspected:	10/01/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	2,070.00 FS	*1,656.00 FS	
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS	
3	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	32.00 FS	*- FS	
4	1		*REAR BUMPER SPOILER	Cut	237.00 FS	*189.60 FS	
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	82.00 FS	*- FS	
6	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	603.00 FS	*- FS	
7	2		*REAR BUMPER BRACKET-LH/RH	Not Necessary	26.00 FS	*- FS	
8	2		*REAR BUMPER GUIDE SECTION OUTER -LH/RH	Not Necessary	134.00 FS	*- FS	
9	2		*REAR PARKING AID SENSOR -INNER /OUTER (NPA)	Not Necessary	0.00 FS	*- FS	
10	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS	
11	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS	
					Total Parts (\$)	3,686.00	1,845.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER TO REPAIR REAR END PANELLING ,RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$)	3,872.00
				1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >