

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/GRB22000062/UGA3Q2**Date:** 11/04/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SLR3234K	<b>Insured Vehicle No :</b>	SLQ2619X
Date of Loss:	31/12/2021	Nature of Claim:	TP
		Claim No:	MFL2022D0000077

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR3234K	Engine No:	LEB5555909
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71029971
Reg. Date:	10/08/2017 (Man. Year: 2017)	Odometer:	105495 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,449.00	3,602.40	4,846.60	57.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,170.00	740.00	38.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,359.00</b>	<b>4,772.40</b>	<b>5,586.60</b>	<b>53.93</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,359.00</b>	<b>3,800.00</b>	<b>6,559.00</b>	<b>63.32</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,207.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,200.00</b>		

INSPECTION

Date of Assignment:	03/01/2022	Choo Motor Spray Painter (HQ)
Date Inspected:	03/01/2022 Inspected At:	1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2022)
<b>Parts:</b>	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLR3234K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,180.00 F	*1,050.00 FL
2	1		*FRONT BUMPER BEAM	Bent	455.00 F	*425.00 FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	198.00 F	*- FL
4	1		*FRONT BUMPER TOW COVER	Serviceable	45.00 F	*- FL
5	2		*FRONT BUMPER SIDE RETAINERS	Necessary	70.00 F	*70.00 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
7	1		*FRONT GRILLE	Cracked	799.00 F	*690.00 FL
8	1		*FRONT GRILLE CHROME	Not Necessary	620.00 F	*- FL
9	1		*HEADLAMP LED O/S	Cracked	2,450.00 F	*1,950.50 FL
10	1		*HEADLAMP LOWER BRACKET O/S	Cracked	99.00 F	*75.50 FL
11	1		*FRONT SUPPORT PANEL	Repair	688.00 F	*- FL
12	1		*FRONT FENDER O/S	Repair	615.00 F	*- FL
13	1		*WIPER WASHER TANK	Deformed	192.00 F	*192.00 FL
14	1		*AIR CON CONDENSER	Not Necessary	988.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,449.00</b>	<b>4,503.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (S\$)</b>	0.00	900.60
<b>Total Parts (S\$)</b>	<b>8,449.00</b>	<b>3,602.40</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	0.00
3	TO REFILL AIR CON GAS	New	100.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	550.00
5	TO PUTTY & SPRAY PAINTING	New	800.00	600.00
<b>Gross Labour Cost (\$)</b>			<b>1,910.00</b>	<b>1,170.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >