

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22000063/KPA3Q2**Date:** 23/06/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SKN7930R	Insured Vehicle No :	SLK7140H
Date of Loss:	31/12/2021	Nature of Claim:	TP
		Claim No:	MFL2022D0000067

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN7930R		
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Engine No:	G4FGEU049848
Reg. Date:	18/07/2014 (Man. Year: 2014)	Chassis No:	KMHDH41CMEU240454
Colour:	Metallic Red	Odometer:	270014 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,577.12	9,128.69	1,448.43	13.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,160.00	3,680.00	480.00	11.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,737.12	12,808.69	1,928.43	13.09
Approved Total (Overridden) (\$\$)		8,000.00		
(\$\$)	14,737.12	8,000.00	6,737.12	45.72
+ GST 7.00/7.00% (\$\$)	1,031.60	560.00	471.60	45.72
Nett Amount (\$\$)	15,768.72	8,560.00	7,208.72	45.72
+ Car Rental (21.0 x S\$100.00/day) (\$\$)		2,100.00		
+ Doc/Search Fee (\$\$)		8.00		
Nett Liability (\$\$)		10,668.00		

INSPECTION

Date of Assignment:	03/01/2022	
Date Inspected:	05/01/2022	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	20.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2022)
Parts:	143	HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN7930R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	459.40 FL	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	303.70 FL	*303.70 FL
3	1		*REAR BUMPER LOWER SKIRT	Cracked	250.10 FL	*250.10 FL
4	2		*REAR BUMPER REFLECTORS	Cracked	56.60 FL	*56.60 FL
5	2		*REAR BUMPER SIDE RETAINERS	Distorted	49.20 FL	*49.20 FL
6	6		*REAR BUMPER CLIPS	Necessary	18.00 FL	*18.00 FL
7	1		*REAR BOOT	Bent	1,840.00 FL	*1,840.00 FL
8	1		*REAR BOOT INNER BOARD	Cracked	84.80 FL	*84.80 FL
9	1		*REAR BOOT INNER SPONGE	Cracked	198.10 FL	*198.10 FL
10	1		*REAR BOOT INNER LOCK	Dented	134.60 FL	*134.60 FL
11	1		*REAR BOOT INNER RUBBER (50%)	Distorted / Dented	63.44 FS	*39.65 FS
12	2		*REAR BOOT HINGES	Bent	188.60 FL	*188.60 FL
13	2		*REAR FENDERS	Buckled	3,713.20 FL	*3,713.20 FL
14	2		*REAR FENDER INNER GARNISHS	Deformed	343.40 FL	*343.40 FL
15	2		*TAILLAMPS	Cracked	776.00 FL	*776.00 FL
16	2		*TAILLAMP PANELS	Bent	343.80 FL	*343.80 FL
17	1		*REAR BOOT LOGO	Necessary	28.10 FL	*28.10 FL
18	1		*REAR BOOT EMBLEM (ELANTRA)	Necessary	48.80 FL	*48.80 FL
19	2		*REAR BOOT REFLECTORS	Cracked	597.60 FL	*597.60 FL
20	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	41.60 FL	*41.60 FL
21	1		*REAR SPARE TYRE COMPARTMENT	Bent / Buckled	878.30 FL	*878.30 FL
22	1		*REAR SPARE TYRE TOP BOARD	Cracked	213.80 FL	*213.80 FL
23	1		*REAR CENTRE PANEL	Bent	454.60 FL	*454.60 FL
24	1		*REAR CENTRE PANEL INNER TOP GARNISH	Distorted	39.00 FL	*39.00 FL
25	1		*REAR AXLE	Serviceable	1,188.70 FL	*- FL
26	1		*REAR RH WHEEL BEARING WITH HUB	Serviceable	352.90 FL	*- FL
27	1		*REAR RH SHOCK ABSORBER	Serviceable	239.20 FL	*- FL
28	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
29	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,145.54	11,340.95
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,568.42	2,212.26
Total Parts (\$\$)	10,577.12	9,128.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	100.00	100.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
3	PANEL BEATING	New	2,100.00	2,000.00
4	PUTTY & RESPRAY PAINTING	New	1,400.00	1,300.00
5	REMOVE & REFIX REAR UNDER CARRIAGE AND EXHAUST PIPE	New	280.00	0.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
7	RUSTPROOFING	New	100.00	100.00
Gross Labour Cost (S\$)			4,160.00	3,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >