8/2/22, 3:18 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG22000064/TGA3Q2

02/08/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900167844 **Claimant Vehicle**

SHC8494U Insured Vehicle No: SMP5153X No:

Date of Loss: 01/01/2022 Nature of Claim: TP Claim No: 2764737957SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC8494U

Make & Model: HYUNDAI AE IONIQ, 1.6 (A) 1ZR0F20005 Engine No:

Reg. Date: 16/03/2020 (Man. Year: 2020) Chassis No: MR2BE3BE800007971

Colour: Odometer: 219339 km Blue

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,450.44	613.60	836.84	57.70
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,040.00	720.00	320.00	30.77
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	2,490.44	1,333.60	1,156.84	46.45
	+ GST 7.00/7.00% (S\$)	174.33	93.35	80.98	46.45
	Nett Amount (S\$)	2,664.77	1,426.95	1,237.82	46.45
	+ Loss of Use (4.5 x S\$50.00/day) (S\$)		225.00		
	+ Car Rental (4.5 x S	\$128.40/day) (S\$)	577.80		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	2,231.75		
	Global Su	m Settlement (S\$)	2,200.00		

INSPECTION

Date of Assignment: 03/01/2022

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 03/01/2022 Inspected At:

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

MOHD TAUFIKH BIN HAMID Chong Pui Lin Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	55.80 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
4	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	94.60 FL	*- FL
6	1		*REAR BUMPER REFLECTOR RH	Not Necessary	41.45 FL	*- FL
7	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
8	1		*REAR REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS
9 E=Fra	1 inchise	part_S=SpcN	*REAR BUMPER NUMBER PLAT W/HOLDER lett. L=ListItemDisc.	Cracked	55.00 FS	*55.00 FS
		parti o opor		Sub Total (S\$)	1,754.30	708.25
	- List Item Discount on L Items 20.00/20.00% (S\$)			303.86	94.65	
				Total Parts (S\$)	1,450.44	613.60
			Report was unsubmitted during	this print-out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	500.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	CHECK LIGHTING AND WIRING	New	60.00	30.00
4	TOWING FEE	New	60.00	60.00
5	TUFF KOTE	New	60.00	0.00
6	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
		Gross Labour Cost (S\$)	1,040.00	720.00
	Report was	s unsubmitted during this print-out.		

< END OF ESTIMATES >