



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDX 938X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PANEL ASSY,RR DR RH (SN)	TO REPAIR SEE LABOUR	1,323.00	-
1	PANEL SUB-ASSY,QUAR (SN)	TO REPAIR SEE LABOUR	1,218.20	-
1	COVER,RR BUMPER (SN)	TO REPAIR SEE LABOUR	589.50	-
1	RETAINER,RR BUMPER R (SN)	SERVICEABLE	116.00	-
1	SEAL,RR BUMPER SIDE (SN)	NOT NECESSARY	58.50	-
1	CLIPS (SN)	NOT NECESSARY	4.30	-
1	WHEEL DISC (SN)	SCRATCHED	2,133.00	2,133.00
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
			5,472.50	2,163.00
	<u>LABOUR</u>			
	REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING.		72.00	72.00
	CONDUCT FULL WHEEL ALIGNMENT.		180.00	180.00
	REMOVE & INSTALL REAR REVERSE SENSOR.	NOT NECESSARY	180.00	-
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	REPAIR & REALIGN RH REAR ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF PANEL ASSY,RR DR RH,PANEL SUB-ASSY,QUAR AND COVER,RR BUMPER.		2,160.00	720.00
	RESPRAY JOB ON RH REAR ACCIDENT AFFECTED AREAS.		2,360.00	1,770.00
			5,132.00	2,922.00
	GRAND TOTAL		10,604.50	5,085.00
	RECOMMENDED COST OF REPAIRS			5,085.00

Report Ref No. CS/SMR22000078/Vvf3n2

THEVAN THOMAS KARTHIKESAVAN

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.