



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 7883D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	PANEL BUMPER PRIMED REAR (SN)	DEFORMED	1,050.65	1,050.65
1	FLAP,TOWING EYE PRIMED (SN)	NOT NECESSARY	43.25	-
1	GUIDE BUMPER,SIDE INNER LEFT (SN)	NOT NECESSARY	161.15	-
1	GUIDE BUMPER,SIDE INNER RIGHT (SN)	NOT NECESSARY	161.15	-
1	SET MOUNTS,PDC SENSOR (SN)	NOT NECESSARY	61.00	-
1	SUPPORT (SN)	NOT NECESSARY	45.75	-
1	CARRIER,BUMPER REAR (SN)	NOT NECESSARY	483.40	-
4	ULTRASONIC SENSOR ALPINE (SN)	NOT NECESSARY	1,532.60	-
4	DECOUPLING RING PDC TORQUE CONVERTER (SN)	NOT NECESSARY	20.60	-
1	TAIL TRIM (SN)	NOT NECESSARY	358.80	-
1	INTERIOR TAIL TRIM (SN)	NOT NECESSARY	281.90	-
23	BLIND RIVET N3 (SN)	NOT NECESSARY	12.65	-
1	CLEANER R1 (100ML) (SN)	NOT NECESSARY	26.15	-
2	KAROSSERIEKLEBSTOFF K5 (SN)	NOT NECESSARY	673.50	-
19	PUNCH RIVET N4 (SN)	NOT NECESSARY	10.45	-
5	SCREW (SF PLUS M5X) (SN)	NOT NECESSARY	2.75	-
1	REINFORCEMENT PLATE,D-PILLAR,LEFT (SN)	NOT NECESSARY	63.25	-
1	REINFORCEMENT PLATE,D-PILLAR,RIGHT (SN)	NOT NECESSARY	63.25	-
1	REAR LIGHT IN TRUNK LID,LEFT (SN)	NOT NECESSARY	195.10	-
1	REAR LIGHT IN THE SIDE PANEL,LEFT (SN)	NOT NECESSARY	278.75	-
1	PLAQUE (BMW 74MM) (SN)	NOT NECESSARY	71.95	-
2	GROMMET (SN)	NOT NECESSARY	1.60	-
1	REAR REFLECTOR,REAR LEFT (SN)	NOT NECESSARY	39.05	-
1	REAR REFLECTOR,REAR RIGHT (SN)	NOT NECESSARY	39.05	-
1	SUNDRIES (SN)	NECESSARY	100.00	80.00
			5,777.75	1,130.65
<u>LABOUR</u>				
TO REPLACE REAR BUMPER AND ATTACHMENTS INCLUDE MAKING GOOD THE BOOT LID AND KNOCKING OUT DENTS CAUSED BY THE ACCIDENT.			2,160.00	720.00
TO SPRAY PAINT REAR BUMPER AND BOOT LID.			1,975.00	680.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE PDC SENSORS AND CONNECTORS INCLUDE RESETTING AND CONDUCTING CHECKS FOR PROPER FUNCTION.		350.00	200.00
	TO CARRY OUT VEHICLE DIAGNOSIS-ABL.	NOT NECESSARY	500.00	-
			4,985.00	1,600.00
GRAND TOTAL			10,762.75	2,730.65
RECOMMENDED COST OF REPAIRS				2,730.65

Report Ref No. CS/AGI22000085/Rtf3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.