LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG22000086/T1VF3E2

07/01/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900246059 **Claimant Vehicle**

FBS5758R Insured Vehicle No: SMQ4022S No:

Date of Loss: 25/12/2021 Nature of Claim: TP Claim No: 0510623475SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBS5758R

Make & Model: YAMAHA MX KING T150. 150cc G3E6E0635328 Engine No:

Reg. Date: 07/06/2021 (Man. Year: 2021) Chassis No: MH3UG0750MK094934

Odometer: Colour: Black 0 km

Engine Capacity: 150 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 60/80 R17 Rear Tyre Size: 60/80 R17 Front Left Side: Rear Left Side: Maxxis 5 mm Maxxis 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/01/2022

Ong Motor Trading (MACPHERSON RD) Date Inspected: 04/01/2022 Inspected At:

No. 464 Macpherson Road

Singapore 368182

Estimated Period of Repair: 5.0 days

MOHD TAUFIKH BIN HAMID Adjuster: Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$12,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT NUMBER PLATE	Bent	0.00 F	*- F
2	1	*FRONT TYRE	* Check	0.00 F	*- F
3	1	*FRONT RIM	Cracked	0.00 F	*- F
4	1	*FRONT TYRE RIM SHAFT	* Check	0.00 F	*- F
5	1	*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
6	1	*FRONT BRAKE DISC	* Check	0.00 F	*- F
7	1	*FRONT FORK ASSY	Bent	0.00 F	*- F
8	1	*FRONT FORK BRACKET	Bent	0.00 F	*- F
9	1	*FRONT HEADLAMP COWLING	Cut	0.00 F	*- F
10	1	*FRONT HEADLAMP	* Check	0.00 F	*- F
11	1	*FRONT WING MIRROR	Cracked	0.00 F	*- F
12	1	*FRONT LH SIGNAL LAMP	Cracked	0.00 F	*- F
13	1	*FRONT RH SIGNAL LAMP	* Check	0.00 F	*- F
14	1	*FRONT TOP FAIRING LIGHT LH	Cracked	0.00 F	*- F
15	1	*STEERONG CONE & BEARING	Necessary	0.00 F	*- F
16	1	*HANDLE BAR	Bent	0.00 F	*- F
17	1	*HANDLE BAR GRIP	Missing	0.00 F	*- F
18	1	*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
19	1	*CLUTCH LEVER	Cut	0.00 F	*- F
20	2	*SIDE FAIRING	Distorted	0.00 F	*- F
21	1	*SIDE FAIRING TOP GARNISH	Cut	0.00 F	*- F
22	1	*SIDE FAIRING LOWER	Cut	0.00 F	*- F
23	1	*CENTER FAIRING FRONT	Cut	0.00 F	*- F
24	1	*REAR FAIRING	* Check	0.00 F	*- F
25	1	*RADIATOR	Bent	0.00 F	*- F
26	1	*FRONT FOOT REST	Cut	0.00 F	*- F
27	1	*FOOT GEAR SHIFTER	Bent	0.00 F	*- F
28	1	*REAR FOOT REST	Cut	0.00 F	*- F
29	1	*REAR BOX	* Check	0.00 F	*-F
30	1	*SET STICKER	Necessary	0.00 F	*- F
F=Fra	anchise part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >