

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22000087/KVF3N2**Date:** 21/01/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001471870

Claimant Vehicle No : SLH2388J**Insured Vehicle No :** SJN8778U

Date of Loss: 31/12/2021

Nature of Claim: TP

Claim No: 267709

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLH2388J**

Make & Model: MERCEDES-BENZ E200 BLUE EFFICIENCY COUPE, 1.8 (A)

Engine No: 27186030595786

Reg. Date: 27/03/2013 (Man. Year: 2012)

Chassis No: WDD2120482A717886

Colour: Black

Odometer: 239089 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35ZR19

Rear Tyre Size: 245/35ZR19

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,212.00	6,795.70	9,416.30	58.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,370.00	1,430.00	51.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,012.00	8,165.70	10,846.30	57.05
Approved Total (Overridden) (\$\$)		6,500.00		
(\$\$)	19,012.00	6,500.00	12,512.00	65.81
+ GST 7.00/7.00% (\$\$)	1,330.84	455.00	875.84	65.81
Nett Amount (\$\$)	20,342.84	6,955.00	13,387.84	65.81

INSPECTION

Date of Assignment: 04/01/2022

Date Inspected: 05/01/2022 Inspected At:

Riverview Auto Services Pte Ltd (HQ)

10, Ang Mo Kio Industrial Park 2A, #04-07 AMK

Autopoint

Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jan 2022)

Parts: 143 MERCEDES-BENZ E200 BLUE EFFICIENCY COUPE 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLH2388J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	2,950.00 F	*2,110.00 FL
2	1		*BOOTLID MERS BADGE	Necessary	135.00 F	*75.00 FL
3	1		*BOOTLID E200 EMBLEM	Necessary	115.00 F	*82.00 FL
4	1		*BOOTLID LOCK	Dented	325.00 F	*325.00 FL
5	1		*REAR BUMPER	Buckled	1,840.00 F	*1,680.00 FL
6	1		*REAR BUMPER PDC REVERSE SENSOR (4 Pcs)	Shorted (2 Pcs only)	1,264.00 F	*450.00 FL
7	1		*REAR BUMPER LOWER SPOILER	Dented/Distorted	668.00 F	*603.00 FL
8	2		*REAR BUMPER CENTRE BRACKETS	Serviceable	58.00 F	*- FL
9	2		*REAR BUMPER SIDE RETAINERS	Serviceable	154.00 F	*- FL
10	2		*TAIL LAMPS	Serviceable	1,750.00 F	*- FL
11	2		*TAIL LAMP LOWER BRACKET	Serviceable	180.00 F	*- FL
12	2		*EXHAUST CHROME END PIPE	Repair	750.00 F	*- FL
13	1		*REAR BUMPER REVERSE SENSOR WIRE HARNES	Serviceable	280.00 F	*- FL
14	1		*EXHAUST CHROME END PIPE BRACKET	N/s Cracked/O/s Serviceable	176.00 F	*88.00 FL
15	2		*HEAD REST	Serviceable	1,960.00 F	*- FL
16	1		*BOOT WEATHERSTRIP	Serviceable	220.00 F	*- FL
17	1		*REAR END PANEL TOP GARNISH	Serviceable	222.00 F	*- FL
18	1		*REAR BUMPER CENTRE TRIM	Serviceable	215.00 F	*- FL
19	1		*REAR BUMPER REINFORCEMENT BEAM	Buckled	865.00 F	*765.00 FL
20	1		*REAR END PANEL	Bent	1,330.00 F	*1,245.00 FL
21	1		*BOOTLID C&C BADGE	Necessary	85.00 FS	*85.00 FS
22	1		*BOOTLID REVERSE CAMERA	Serviceable	480.00 FS	*- FS
23	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
24	4		*EXHAUST CHROME END PIPE BRACKET RIVETS	Not Necessary	80.00 FS	*- FS
25	1		*END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 16,212.00 7,538.00
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 742.30

Total Parts (\$\$) 16,212.00 6,795.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & REPAIR THE ACCIDENT AREA	New	1,200.00	600.00
2	TO REPAIR & RESET HEADREST	New	250.00	0.00
3	TO INSTALL REVERSE CAMERA & CHECK FOR PROPER FUNCTION	New	80.00	50.00
4	TO SPRAY PAINT BOOTLID,REAR BUMPER & REAR END PANEL	New	900.00	660.00
5	TO CHECK WITH MERS STAR DIAGNOISE COMPUTER & CLEAR ALL FAULT CODE	New	250.00	0.00
6	TO CARRY OUT ANTI-RUST TREATMENT AT THE ACCIDENT AREA	New	120.00	60.00
Gross Labour Cost (\$)			2,800.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >