

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIG22000090/AQF3N2**Date:** 10/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210080598
<b>Claimant Vehicle No :</b>	SGZ6595R	<b>Insured Vehicle No :</b>	SKN8200H
Date of Loss:	27/12/2021	Nature of Claim:	TP
		Claim No:	3372347575SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGZ6595R</b>	Engine No:	4G18JL6386
Make & Model:	MITSUBISHI LANCER, 1.3 (A)	Chassis No:	JMYSTCS3A8U003272
Reg. Date:	13/11/2007 (Man. Year: 2007)	Odometer:	299657 km
Colour:	Red		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,041.09	1,437.87	1,603.22	52.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	950.00	1,450.00	60.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,441.09</b>	<b>2,387.87</b>	<b>3,053.22</b>	<b>56.11</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,441.09</b>	<b>1,900.00</b>	<b>3,541.09</b>	<b>65.08</b>

INSPECTION

Date of Assignment:	04/01/2022	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883
Date Inspected:	06/01/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	821.70 FL	*696.00 FL
2	1		*REAR BUMPER SIDE HOLDER	O/s Necessary	88.00 FL	*44.00 FL
3	1		*REAR BUMPER LOWER LIP	Cracked	480.00 FL	*480.00 FL
4	1		*REAR RH LAMP	Cut	344.30 FL	*344.30 FL
5	1		*REAR RH FENDER	Repair	690.80 FL	*- FL
6	1		*REAR END PANEL	Not Necessary	465.30 FL	*- FL
7	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
8	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,330.10	1,594.30
- List Item Discount on L Items 10.00/10.00% (\$)	289.01	156.43
Total Parts (\$)	3,041.09	1,437.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REINSTALL REVERSE SENSOR	New	200.00	50.00
2	REMOVE & REINSTALL BOOTLID INNER GARNISH	New	200.00	0.00
3	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,000.00	300.00
4	RESPRAY PAINTING	New	1,000.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,400.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >