

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG22000092/BGA3Q2**Date:** 15/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800156762
<b>Claimant Vehicle No :</b>	SMR7063Z	<b>Insured Vehicle No :</b>	SJT8522J
Date of Loss:	31/12/2021	Nature of Claim:	TP
		Claim No:	5163682724SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMR7063Z</b>	Engine No:	LEB6744068
Make & Model:	HONDA VEZEL HYBRID, 1.5 x (A)	Chassis No:	RU31324056
Reg. Date:	17/01/2020 (Man. Year: 2018)	Odometer:	89620 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,633.36	3,582.24	12,051.12	77.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,350.00	1,860.00	3,490.00	65.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,983.36</b>	<b>5,442.24</b>	<b>15,541.12</b>	<b>74.06</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,350.00</b>		
<b>(S\$)</b>	20,983.36	4,350.00	16,633.36	79.27
<b>+ GST 7.00/7.00% (S\$)</b>	1,468.84	304.50	1,164.34	79.27
<b>Nett Amount (S\$)</b>	<b>22,452.20</b>	<b>4,654.50</b>	<b>17,797.70</b>	<b>79.27</b>
<b>+ Car Rental (9.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		963.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,624.95</b>		

INSPECTION

Date of Assignment:	04/01/2022	
Date Inspected:	04/01/2022	Inspected At: 160 SIN MING DR #01-14
Estimated Period of Repair:	7.0 days	Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

**Adjuster:** Lim Teow Guan**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,840.00 FL	*951.00 FL
2	1		*TAILGATE LOGO	Necessary	95.00 FL	*45.00 FL
3	1		*TAILGATE EMBLEM VEZEL	Necessary	89.30 FL	*57.00 FL
4	1		*TAILGATE EMBLEM HYBRID	Necessary	88.00 FL	*66.30 FL
5	1		*TAILGATE OUTER GARNISH	Not Damaged	455.00 FL	*- FL
6	2		*TAILGATE LAMP	Not Damaged	1,580.00 FL	*- FL
7	1		*TAILGATE INNER LOCK	Jammed	248.60 FL	*180.20 FL
8	1		*TAILGATE INNER LOCK STICKER	Not Damaged	81.00 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Broken	498.20 FL	*242.30 FL
10	1		*TAILGATE HANDLE POCKET GARNISH	Not Damaged	98.00 FL	*- FL
11	2		*TAILGATE WINDSCREEN MOULDING SIDE	Necessary	236.00 FL	*164.00 FL
12	1		*TAILGATE WINDSCREEN MOULDING TOP	Necessary	145.00 FL	*100.00 FL
13	1		*TAILGATE WINDSCREEN MOULDING BOTTOM	Necessary	145.00 FL	*100.00 FL
14	1		*TAILGATE WEATHERSTRIP	Torn	185.00 FL	*162.30 FL
15	1		*TAILGATE ANTENNA SENSOR	Not Damaged	245.60 FL	*- FL
16	1		*TAILGATE BUZZER	Broken	185.00 FL	*107.10 FL
17	1		*REAR BUMPER	Broken	1,185.00 FL	*762.70 FL
18	2		*REAR BUMPER SIDE RETAINER	Necessary	176.00 FL	*150.00 FL
19	2		*REAR BUMPER SIDE GARNISH	Broken	491.60 FL	*195.00 FL
20	2		*REAR BUMPER BRACKET	No such part	272.00 FL	*- FL
21	2		*REAR BUMPER REFLECTOR	Broken	374.00 FL	*55.00 FL
22	1		*REAR BUMPER LOWER SPLASH GUARD	Not Damaged	150.30 FL	*- FL
23	1		*REAR END PANEL	Dented	985.00 FL	*517.30 FL
24	1		*REAR END PANEL TOP GARNISH	Broken	184.00 FL	*122.60 FL
25	1		*SPARE TYRE PANEL	Not Damaged	782.60 FL	*- FL
26	1		*SPARE TYRE PANEL TOP BOARD	Not Damaged	486.00 FL	*- FL
27	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	1,960.00 FL	*- FL
28	2		*TAILLAMP	Not Damaged	1,778.00 FL	*- FL
29	1		*EXHAUST PIPE	Not Damaged	895.00 FL	*- FL
30	2		*EXHAUST MOUNTING	Not Damaged	85.00 FL	*- FL
31	1		*EXHAUST HEAT SHIELD	Not Damaged	185.00 FL	*- FL
32	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
33	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
34	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
35	2		*TAILGATE LAMP CLIPS	Not Necessary	100.00 FS	*- FS
36	2		*TAILGATE LAMP SEAL	Not Necessary	120.00 FS	*- FS
37	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
39	1		*TAILGATE WINDSCREEN INNER SEAL	No such part	60.00 FS	*- FS
40	1		*TAILGATE WINDSCREEN CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
42	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
43	2		*REAR BUMPER SIDE GARNISH CLIPS	Necessary	100.00 FS	*20.00 FS
44	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
45	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
46	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
47	1		*SPARE TYRE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
48	2		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
49	2		*REAR FENDER ARCH GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
50	2		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS
51	2		*TAILLAMP CLIPS	Not Necessary	100.00 FS	*- FS
52	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
53	1		*REAR NUMBER PLATE W/CASING	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 18,874.20 4,377.80**

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	R&R REVERSE CAMERA	New	100.00	0.00
5	R&R EXHAUST PIPE	New	150.00	0.00
6	UPHOLSTERY	New	300.00	0.00
7	CHECK WIRING	New	200.00	0.00
8	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
9	PANEL BEATING	New	1,800.00	1,000.00
10	RUST PROOFING	New	200.00	0.00
11	SPRAY PAINTING	New	1,800.00	600.00
			<b>Gross Labour Cost (S\$)</b>	<b>5,350.00</b>
				<b>1,860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >