



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 6628R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT NUMBER PLATE GARNISH (CONSISTENT)	DEFORMED	103.00	103.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,516.00	1,516.00
2	FRONT BUMPER SIDE HOLDER @\$105.00 (CONSISTENT)	NOT NECESSARY	210.00	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	689.00	-
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	183.00	183.00
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	NOT NECESSARY	201.00	-
2	FRONT BUMPER SIDE GRILLE @\$72.00 (CONSISTENT)	N/S DEFORMED	144.00	72.00
4	FRONT BUMPER SENSOR @\$245.00 (CONSISTENT)	DAMAGED (1PC ONLY)	980.00	245.00
1	FRONT BUMPER INNER TOP COVER (CONSISTENT)	CRACKED	242.00	242.00
1	FRONT BUMPER LOWER GARNISH (CONSISTENT)	DEFORMED	394.00	394.00
1	FRONT GRILLE (CONSISTENT)	CRACKED	895.00	895.00
1	FRONT GRILLE LOGO (CONSISTENT)	CUT	112.00	112.00
1	FRONT GRILLE OUTER CHROME (CONSISTENT)	CRACKED	288.00	288.00
1	HEADLAMP LH (CONSISTENT)	CRACKED	3,125.00	3,125.00
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	2,092.00	-
1	BONNET LOGO (CONSISTENT)	NECESSARY	86.00	86.00
1	FRONT LH FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	1,042.00	-
	LESS 10% DISCOUNT		-	-726.10
			12,302.00	6,534.90
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	DENTED	30.00	30.00
1	FRONT NUMBER PLATE HOLDER (SN) (CONSISTENT)	DEFORMED	30.00	30.00
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT GRILLE CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
			130.00	130.00
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BONNET AND FRONT LH FENDER.		1,000.00	500.00

Report Ref No. CS/ASM22000093/Avy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,000.00	600.00
	WIRING.		100.00	30.00
	TO REMOVE FRONT BUMPER SENSOR.		100.00	60.00
	TO PERFORM DIAGNOSTIC TEST.		200.00	150.00
			2,400.00	1,340.00
<b>GRAND TOTAL</b>			<b>14,832.00</b>	<b>8,004.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,400.00</b>

Report Ref No. CS/ASM22000093/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.