

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 3922Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	BENT	616.85	605.00
1	REAR PANEL (CONSISTENT)	BENT	348.50	348.50
1	REAR LAMP N/S (CONSISTENT)	CUT	393.40	289.70
1	REAR SPARE TYRE BOARD (CONSISTENT)	SERVICEABLE	540.40	-
1	SET REAR LICENSE PLATE LAMP @\$18.25 (CONSISTENT)	SERVICEABLE	36.35	-
2	REAR BUMPER SIDE RETAINER @\$25.00 (CONSISTENT)	N/S CRACKED	50.00	25.00
1	REAR FLOOR PANEL (CONSISTENT)	BENT	630.00	630.00
2	FRONT HEADLAMP @\$630.00 (CONSISTENT)	MTG CRACKED	1,260.00	973.70
1	FRONT BUMPER (CONSISTENT)	BUCKLED	728.75	620.15
1	REAR BUMPER LOWER GUIDE (CONSISTENT)	DISTORTED / CRACKED	471.25	385.55
1	REAR BUMPER TOW COVER (CONSISTENT)	MISSING	21.55	21.55
	LESS 15% DISCOUNT		-	-584.87
			5,097.05	3,314.28
	SPECIAL NETT ITEMS			
1	REAR BOOTLID RUBBER (\$130.13) (50%) (SN) (CONSISTENT)	DISTORTED / DENTED	130.13	65.06
1	REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
1	REVERSE CAMERA (SN) (CONSISTENT)	SERVICEABLE	250.00	-
1	GREDDY EXHAUST (SN) (CONSISTENT)	BENT	1,300.00	1,300.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	CRACKED	30.00	25.00
			1,990.13	1,590.06
	<u>LABOUR</u>			
	SPRAY PAINTING.		1,000.00	800.00
	LABOUR TO RENEW ABOVE PARTS.		1,200.00	1,100.00
	ANTI RUST.		50.00	50.00
			2,250.00	1,950.00
	GRAND TOTAL		9,337.18	6,854.34

Report Ref No. CS/ASM22000094/Kty3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		5,450.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/ASM22000094/Kty3e2

**KONG SENG CHEONG** 

**Licensed Appraiser**