

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: MS FIRST CAPITAL INSURANCE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SHB128K [YOUR INSURED] & JGG9316 [OUR CLIENT]
ON 20/01/2021.

ESTIMATED REPAIR COSTS FOR JGG9316

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE <i>Dent</i>	1174.40	\$ 2,984.50 ✓
1PC	TAILGATE WINDSCREEN MOULDING <i>H/c</i>	187.00	\$ 294.10 ✓
1PC	TAILGATE CENTER GARNISH <i>st</i>	293.20	\$ 718.00 ✓
2PCS	TAILGATE LAMP LH / RH @ \$984.00 EACH <i>H/S CRACK O/S HH</i>		\$ 1,968.00 ✓ 450.00
2PCS	TAILGATE LAMP TOP GARNISH LH / RH @ \$510.00 EACH <i>H/S CRACK</i>		\$ 1,020.00 ✓ 190.60
1PC	TAILGATE INNER TRIM BOARD <i>HH</i>	O/S HH	\$ 717.00 X
1PC	TAILGATE WEATHER STRIP <i>SV</i>		\$ 429.00 X
1PC	TAILGATE LOCK <i>HH</i>		\$ 495.00 X 435.40
2PCS	TAIL LAMP LH / RH @ \$1,194.00 EACH <i>H/S broken O/S HH</i>		\$ 2,388.00 ✓
2PCS	REAR SIGNAL LAMP LH / RH @ \$914.00 EACH <i>H/S broken O/S HH</i>		\$ 1,828.00 ✓ 341.80
1PC	REAR BUMPER <i>broken</i>	461.00	\$ 1,698.00 ✓
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$198.00 EACH <i>SV</i>		\$ 396.00 X
1PC	REAR BUMPER BEAM <i>Dent</i>	350.00	\$ 582.00 ✓
1PC	REAR END PANEL <i>ray</i>		\$ 2,481.00 X
1PC	REAR END PANEL TOP GARNISH <i>HH</i>		\$ 492.00 X
1PC	REAR FLOOR PANEL EXTENSION <i>HH</i>		\$ 4,985.00 X
1PC	REAR EXHAUST PIPE <i>HH</i>		\$ 1,789.00 X
1PC	REAR EXHAUST MOUNTING <i>HH</i>		\$ 291.00 X
1PC	REAR EXHAUST HEAT SHIELD <i>HH</i>		\$ 485.00 X

3883.40
10% 3495.06 //

PARTS SUM: \$ 26,040.60
PARTS LESS 10%: \$ 2,604.06
PARTS TOTAL: \$ 23,436.54

LABOUR & SPECIAL NETT ITEMS

* TO SUPPLY REAR WINDSCREEN SEALANT *H/c*

\$ 80.00 40/-

* TO SUPPLY REAR WINDSCREEN DAMPING SEAL HH	\$ 30.00 X
* TO SUPPLY REAR WINDSCREEN INNER SEAL HH	\$ 50.00 X
* TO SUPPLY TAILGATE INNER TRIM CLIPS HH	\$ 50.00 X
* TO SUPPLY TAILGATE LAMP CLIPS HH	\$ 50.00 X
* TO SUPPLY TAIL LAMP CLIPS HH	\$ 50.00 X
* TO SUPPLY REAR SIGNAL LAMP CLIPS HH	\$ 80.00 X
* TO SUPPLY REAR BUMPER CLIPS HLC	\$ 50.00 15/-
* TO SUPPLY REAR END PANEL SEALANT HLC HH	\$ 80.00 40/-
* TO SUPPLY REAR FLOOR PANEL EXTENSION SEALANT HH	\$ 80.00 X
* TO SUPPLY TAILGATE CENTER STICKER MF	\$ 200.00 X
* TO SUPPLY 1 SET REVERSE SENSOR Dam	\$ 300.00 200/-
* TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 HH
* TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2400.00 700/-
* TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2400.00 600/-
* TO TUFF COAT DAMAGED AREAS	\$ 150.00 40/-
* TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	\$ 500.00 120/-
* TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ 150.00 60/-
* TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	\$ 120.00 40/-
* TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	\$ 400.00 HH
* TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 30/-
* TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00 HH

LABOUR & S/N TOTAL: \$ 8,020.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 31,456.54

05/01/2022 @ 1630h
H/A Antur

2/3 June 5 days.

Juan

LKK And

S

Check MV / Repair Unit

Check damage consistency

Check part prices.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Limit 3.5K.