

GBA8209J Mit L200 D/C

not items

not added
due
5/1/22
2/5 @ 4500/
6 days

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy NS	\$ 1,650.00 X
2	1	Rear tailgate panel 100 1615	\$ 2,655.00 ✓
3	1	Rear right fender assy R	\$ 2,879.00 X
4	1	Rear left fender assy R	\$ 2,879.00 X
5	1	Rear lower panel Body 100 948	\$ 1,650.00 ✓
6	1	Rear right side lamp 11	\$ 189.00 X
7	1	Rear reflector 115 320 115.00	\$ 189.00 ✓
8	1	Rear centre opening handle with lamp 11	\$ 330.00 X
9	1	Rear centre logo 111 65.00	\$ 90.00 ✓
10	1 set	Rear bumper bracket NS	\$ 250.00 X
11	2	Rear no plate lamp 11	\$ 88.00 X
12	1	Rear left taillamp 11	\$ 665.00 X
13	1	Rear right taillamp 11	\$ 665.00 X
14	3	Rear tailgate hinges 11	\$ 120.00 X
15	1 set	Rear tailgate inner lock 11	\$ 193.00 X
16	1	Rear spare tyre bracket holder 11	\$ 365.00 X
17	1	Rear spare tyre holder lock 11	\$ 166.00 X
			\$ 15,023.00
Less 10%			\$ 1,502.30
			\$ 13,520.70

Special Nett Items

1	1	Rear tailgate aluminium inner plate 11	\$ 1,250.00 X
2	1	Rear left fender aluminium inner plate 11	\$ 1,600.00 X
3	1	Rear right fender aluminium inner plate 11	\$ 1,600.00 X
4	1 set	Rear spare tyre 11	\$ 450.00 X
1 set 5	2	Rear reverse sensor 11 should	\$ 300.00 200
6	1	Rear third brake lamp 11	\$ 350.00 X
7	1	Rear tailgate '70km/h' sticker 111	\$ 30.00 10
8	1	Rear lower bar Bent	\$ 1,850.00 800
9	1	Rear no plate Bent	\$ 80.00 40
			\$ 7,510.00

Total Parts**\$ 21,030.70**

GBA8209J Mit L200 D/C

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,600.00	1000
2	To putty and spray painting rear portion.	\$ 1,600.00	1000
3	To check rear lighting and wiring.	\$ 50.00	20
4	To apply anti rust proofing to rear affected area.	\$ 150.00	60
5	To remove and install rear reverse sensor.	\$ 80.00	50
6	To remove and install rear tailgate lock mechanism.	\$ 11 80.00	X
7	To remove and install rear aluminium inner plate to facilitate the repair.	\$ 11 350.00	X
8	To remove and install both side top railing to facilitate the repair.	\$ 11 350.00	X
9	To apply side black sticker to both fender assy.	\$ 11 600.00	X
10	To conduct chassis alignment.	\$ 11 350.00	X
11	Towing service.	\$ 11 120.00	X
Total labour :		\$ 5,330.00	

Total parts : \$ 21,030.70

Total labour : \$ 5,330.00

Total repair cost : \$ 26,360.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-2740
 102
 P-2466
 S.N-1050
 L-2130
 5646
 202
 4516