

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI22000104/BVY3N2**Date:** 08/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00043582102
Claimant Vehicle No :	GBC2720C	Insured Vehicle No :	GBB5978L
Date of Loss:	02/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200059/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC2720C	Engine No:	ZD30293727K
Make & Model:	NISSAN CABSTAR, 3.0 (M)	Chassis No:	JN1SC2F24Z0850173
Reg. Date:	31/10/2011 (Man. Year: 2011)	Odometer:	226261 km
Colour:	Silver		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165R13	Rear Tyre Size:	195R15C
Front Left Side:	ROADMARCH 4 mm	Rear Left Side:	Windforce 4 mm
Front Right Side:	ROADMARCH 4 mm	Rear Right Side:	Windforce 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/01/2022		
Date Inspected:	05/01/2022	Inspected At:	Assure Auto (HQ) B14 AMK BLK B 569116 Singapore 569116
Estimated Period of Repair:	12.0 days		

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$11,000.00
-\$12,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Feb 2022)	
Parts:	N/A	NISSAN CABSTAR 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC2720C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >