

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22000106/BVF3E2**Date:** 16/03/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001470068		
Claimant Vehicle No :	SKP80D	Insured Vehicle No :	PC4050Z		
Date of Loss:	31/12/2021	Nature of Claim:	TP	Claim No:	267687

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP80D		
Make & Model:	MERCEDES-BENZ E300 AMG LINE (R19 LED), 2.0 (A)	Engine No:	27492031104375
Reg. Date:	15/09/2017 (Man. Year: 2017)	Chassis No:	WDD2383482F012859
Colour:	Blue	Odometer:	84087 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R20	Rear Tyre Size:	275/30 R20
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,583.10	6,106.01	4,477.09	42.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,760.00	1,840.00	2,920.00	61.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,343.10	7,946.01	7,397.09	48.21
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	15,343.10	5,000.00	10,343.10	67.41
+ GST 7.00/7.00% (S\$)	1,074.02	350.00	724.02	67.41
Nett Amount (S\$)	16,417.12	5,350.00	11,067.12	67.41

INSPECTION

Date of Assignment:	04/01/2022	
Date Inspected:	05/01/2022 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	7.0 days	

Adjuster: Lim Teow Guan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2022)

Parts: 143 MERCEDES-BENZ E300 AMG LINE (R19 LED) 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKP80D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Dented	2,053.00 FL	*2,053.00 FL
2	1		*RH FRONT DOOR WEATHERSTRIP	Not Damaged	156.00 FL	*- FL
3	1		*REAR WINDSCREEN GLASS WITH RUBBER MOULDING	Not Necessary	1,278.00 FL	*- FL
4	1		*RH REAR FENDER	Dented	3,015.00 FL	*2,655.12 FL
5	1		*SET RH REAR FENDER RIVETS	Not Necessary	32.00 FL	*- FL
6	1		*RH REAR FENDER GLASS WITH RUBBER MOULDING	Not Necessary	456.00 FL	*- FL
7	1		*RH REAR FENDER INNER TRIM BOARD	Not Damaged	631.00 FL	*- FL
8	1		*RH SIDE ROCKER PANEL GARNISH	Broken	465.00 FL	*465.00 FL
9	1		*SET RH SIDE ROCKER PANEL GARNISH CLIPS	Necessary	85.00 FL	*30.00 FL
10	1		*REAR BUMPER (AMG)	Broken	1,518.00 FL	*1,518.00 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
12	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	70.00 FS	*- FS
13	1		*REAR WINDSCREEN GLASS INNER SEAL	Not Necessary	50.00 FS	*- FS
14	1		*RH REAR FENDER JOINT SEALANT	Necessary	80.00 FS	*30.00 FS
15	1		*RH REAR SPORT RIM	Not Damaged	1,500.00 FS	*- FS
16	1		*RH REAR FENDER GLASS SEALANT	Not Necessary	60.00 FS	*- FS
17	1		*RH REAR FENDER GLASS INNER SEAL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,559.00	6,781.12
- List Item Discount on L Items 10.00/10.00% (S\$)	975.90	675.11
Total Parts (S\$)	10,583.10	6,106.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,600.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,400.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	80.00	0.00
5	REMOVE AND REINSTALL RH FRONT DOOR INNER MECHANISM TO NEW DOOR	New	180.00	80.00
6	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	120.00
7	REMOVE AND REINSTALL ROOF LINING, SEATS, CARPET, REAR INNER TRIMS AND BOARDS TO ASSIST REPAIR	New	450.00	0.00
8	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSORS AND WIRE HARNESS TO ASSIST REPAIR	New	120.00	60.00
9	RESET AND DIAGNOSE CONTROL UNIT AND FAULT CODE AFTER REPAIR	New	380.00	0.00
10	REMOVE AND REPLACE RH REAR FENDER GLASS WITH RUBBER MOULDING TO ASSIST REPAIR	New	250.00	80.00
Gross Labour Cost (\$\$)			4,760.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >