

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22000107/GEA3Q2**Date:** 07/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MPC0000586_03
Claimant Vehicle No : SJR319T **Insured Vehicle No :** SLE6619H
 Date of Loss: 31/12/2021 Nature of Claim: TP Claim No: MPC2022D0000110

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR319T**
 Make & Model: TOYOTA VIOS, 1.5 G (A) Engine No: 1NZX918056
 Reg. Date: 05/06/2009 (Man. Year: 2009) Chassis No: MR053HY9305116311
 Colour: Black Odometer: 348936 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,992.92	1,752.81	1,240.11	41.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	900.00	550.00	37.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,442.92	2,652.81	1,790.11	40.29
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	4,442.92	2,100.00	2,342.92	52.73
+ GST 7.00/7.00% (S\$)	311.00	147.00	164.00	52.73
Nett Amount (S\$)	4,753.92	2,247.00	2,506.92	52.73
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Loss of Earnings (4.0 x S\$40.00/day) (S\$)		160.00		
(S\$)		2,647.00		
Liabile Amount (50.00%) (S\$)		1,323.50		

INSPECTION

Date of Assignment: 04/01/2022
 Date Inspected: 05/01/2022 Inspected At: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)
 Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT
 Singapore 417800
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2022)
Parts: 143	TOYOTA VIOS 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJR319T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	422.02 FL	*422.02 FL
2	1		*FRONT BUMPER LOWER SPOILER	Repair	337.50 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Deformed	68.30 FL	*68.30 FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Deformed	68.30 FL	*68.30 FL
5	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	287.90 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	86.57 FL	*- FL
7	1		*FRONT HEADLAMP RH	Cracked	397.60 FL	*397.60 FL
8	1		*FRONT FENDER RH	Buckled	551.30 FL	*551.30 FL
9	1		*FRONT FENDER INNER SHIELD RH	Deformed	95.60 FL	*95.60 FL
10	1		*FRONT DOOR RH	Repair	482.60 FL	*- FL
11	1		*FRONT BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
12	1		*FRONT NUMBER PLATE	Not Necessary	45.00 FS	*- FS
13	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 FS	*20.00 FS
14	1		*WHEEL RIM	Cut	350.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,272.69	1,913.12
- List Item Discount on L Items 10.00/10.00% (\$\$)	279.77	160.31
Total Parts (\$\$)	2,992.92	1,752.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS TO RE-ADJUST TO THE ORIGINAL USING POWER TOOLS	New	800.00	400.00
2	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	650.00	500.00
Gross Labour Cost (\$\$)			1,450.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >